



U.S. Department of Transportation

National Highway Traffic Safety Administration

Dear Crash Data Researchers/Users:

Thank you for choosing crash data from the National Highway Traffic Safety Administration (NHTSA) for your research or other use. The information contained in this motor vehicle crash report is collected, maintained and distributed in accordance with Public Law 89-564. In accordance with this Public Law, NHTSA is required not to release any case information until completion of quality control procedures. These procedures include a review of the case material to extract all names, licenses and registration numbers, non-coded interview material, non-research related researcher comments in the margins, non-factual data, and the production number portion of the vehicle identification number (VIN).

If you requested NHTSA to query its database files in order to identify a specific crash, then that query was made using non-personal descriptors you provided for use in our search. This motor vehicle crash may have been identified from a data search and matches the general, non-personal descriptors you provided, but we cannot confirm that this is the specific crash report you requested.

If you have any questions with regard to the above procedures, please contact the Field Operations Branch, Crash Investigation Division, National Center for Statistics and Analysis at 202-366-4820. Again, please be advised that we cannot confirm that this is the case that you have specifically requested nor can we certify the information to be correct.

*** *** ***



Case Vehicle (A): 1998 Chevrolet

Type: Malibu LS, 4-door sedan Driver: 51-year-old female

CDC: 11-LFEW-2, 12-RYES-1

Veh. (B): 1997 Chevrolet

Type: Sierra C1500 4 x 2, extended cab pickup

Driver: 53-year-old male

CDC: 99-0000-0

SITUATION

(Slide 1) It was daylight, the skies were cloudy, and (slide 2) the 2-lane east-west, asphalt road surface was dry and free of defects. Case vehicle (A) was traveling west at an unknown speed in the westbound lane. Vehicle (B) was stopped facing north in the northbound lane of a north-south road at its intersection with the east-west road. As case vehicle (A) approached the intersection of the two roads, vehicle (B) pulled out and began to proceed through the intersection. (Slide 3) The driver of case vehicle (A) failed to stop the vehicle at the intersection even though there was a stop sign and flashing red light. The front of vehicle (B) struck the front-left fender of case vehicle (A). (Slide 4) Following the impact, case vehicle (A) veered to the right, went through a ditch (slide 5) and up on a lawn, and sideswiped a utility pole with its right side. The driver of case vehicle (A) was transported by ambulance to a local area hospital. The driver of vehicle (B) was treated at the scene.

GENERAL VEHICLE DAMAGE AND ESTIMATED CRASH SEVERITIES

(Slide 6) Damage to case vehicle (A) was moderate. (Slide 7) Direct damage to case vehicle (A) began at the left-front bumper corner and (slide 8) extended 201 cm down the left side to the forward portion of the left front door. The maximum crush was 10 cm and occurred just forward of the left A-pillar.

Using the WinSMASH accident-reconstruction program, and a crush profile estimated for case vehicle (A), the impact severity shown in the following table was calculated:

		Calculated Velocity Change - kph (mph)				
Vehicle	Variable	Total	Longitudinal	Latitudinal		
Case Vehicle (A)	EBS	16 (10)	-15 (-9)	5 (3)		

DESCRIPTION OF DAMAGE TO CASE VEHICLE (A)

Exterior

On the left side, (slide 9) the fender and lower A-pillar were damaged, and the front wheel was damaged and missing. The left-front door was jammed closed, but had been pried open by rescue personnel. (Slide 10) The left-side wheelbase was increased 3 cm.

In the front, (slide 11) the left headlight assembly, the bumper cover, the bumper and the hood were damaged. (Slide 12) There was a crack along the left portion of the windshield due to contact by the left fender. (Slide 13) There was no other damage to the windshield.

On the right side, (slide 14) direct damage from sideswiping the utility pole began 126-cm rear of the right-front bumper corner, and extended 179-cm rearward, including both doors. The maximum crush from the sideswipe contact was 1 cm, and the wheelbase was increased 2 cm.

(Slide 15) There was no damage to the rear of the vehicle.

Interior

This vehicle was equipped with steering-wheel and passenger frontal-impact airbags, and (slides 16, 17, 18, 19 and 20) both deployed during the left-side impact. (Slides 21, 22, 23, 24, 25 and 26) There was no damage to the steering-wheel or the passenger airbag module covers. (Slides 27 and 28) The passenger airbag module cover contacted, but did not crack the windshield. (Slides 29 and 30) The lower right portion of the steering-wheel rim was bent forward, but there was no damage to the spokes. (Slides 31 and 32) The plastic cover on the upper left A-pillar was cracked. (Slides 33, 34, 35, 36, 37, 38 and 39) There were no intrusions and no other interior damage.

OCCUPANT KINEMATICS AND INJURIES

(Slide 40) The 5-ft, 5-in, 340-lb, 51-year-old female driver was *not* wearing the three-point belt and the frontal-impact airbag deployed. There were no witness marks on the plastic D-ring, (slide 41) and there were no scratches on the metal latch plate that would indicate belt use.

On impact, the driver moved forward and to the left, relative to the vehicle interior. She sustained a contusion to the center of her chest and a contusion under her right breast, probably

due to contact by the deploying airbag. The driver sustained a contusion to the top of her abdomen, probably due to contact with the steering-wheel rim, (slide 42) as evidenced by the deformed steering-wheel rim, or possibly due to contact by the deploying airbag. She sustained a strain to the lumbar area of her back due to impact forces. She sustained abrasions to the medial aspect of her left forearm and upper arm due to contact by the deploying airbag, (slide 43) as indicated by a material transfer marks on the lower left portion of the airbag fabric. She sustained an abrasion to her left knee due to contact with the knee bolster, (slide 44 and 45) as evidenced by a scuff mark on the plastic knee bolster cover.

The following table and attached drawing (slide 46) summarize the injuries for the driver of case vehicle (A).

Occupant: Driver Restraints: 3-point belt <u>not</u> worn; airbag deployed

Age: 51 years Stature: 165 cm (5 ft, 5 in)

Gender: Female

Mass: 154 kg (340 lb)

		Injury Source		
Injury Description	A.I.S.	Definite	Probable	Possible
Contusion, center chest	1		Airbag	
Contusion, under right breast	1		Airbag	
Lumbar strain	1			Impact forces
Contusion, top of abdomen	1		Steering-wheel rim	Airbag
Abrasions, medial aspect of left forearm and upper arm	1		Airbag	
Abrasion, left knee	1		Knee bolster	
Maximum A.I.S. Level	1			
Injury Severity Score	<u>2</u>			

Duplicate columns 1-8 Module G I Format from the previous card. 9 10	0 2	GENERAL INFORMATION	GI-1
TIME DATE OF COLLISION	у у	ENVIRONMENTAL CONDITIONS CONSTRUCTION ZONE (0) NO (1) YES (9) UNKNOWN ROAD ALIGNMENT VERTICAL PLANE (1) LEVEL (2) CREST OF HILL (3) SLOPE (2%) (4) BOTTOM OF HILL	33
STATE FIPS CODE AREA (1) URBAN (2) RURAL (9) UNKNOWN	25 26 2 27	(9) UNKNOWN ROAD ALIGNMENT HORIZONTAL PLANE (1) STRAIGHT (2) CURVE (3) T - SHAPED (4) Y - SHAPED (7) OTHER: (9) UNKNOWN	35
ENVIRONMENTAL CONDITIONS LIMITED-ACCESS HIGHWAY (0) NO (1) YES (9) UNKNOWN ROAD, TOTAL TRAFFIC LANES	<u>O</u> 28	SURFACE COVERING (10) DRY (21) WATER - DAMP (22) WATER - WET (23) WATER - PUDDLED (29) WATER - AMOUNT UNKNOWN	36 37
(FOR CASE VEHICLE) (1) 1-LANE (2) 2-LANES (3) 3-LANES (4) 4 OR MORE LANES (5) DIVIDED, 4 OR MORE LANES (6) PARKING LOT/DRIVEWAY (7) OTHER: (9) UNKNOWN	2 20	(31) SNOW - LOOSE (32) SNOW - PACKED (39) SNOW - CONDITION UNKNOWN (41) ICE (51) SLUSH (61) SPILLED GRAVEL (71) OTHER: (99) UNKNOWN VISIBILITY LIMITATION (FOR CASE VEHICLE)	
INTERSECTING RD, TOTAL LANES CHOOSE FROM ABOVE LIST, OR (8) NOT APPLICABLE TYPE OF ROAD SURFACE (1) ASPHALT (2) CONCRETE (3) GRAVEL	2 30 1 31	(0) NONE (1) CLOUDY/DARK (2) FOG (3) SMOKE (4) WINDSHIELD CONDITION (5) GLARE (6) RAIN (7) OTHER: (8) ICE/SNOW (9) UNKNOWN	38
(4) MORE THAN ONE (CIRCLE EACH) (7) OTHER: (9) UNKNOWN ROAD DEFECTS (0) NO (1) YES (9) UNKNOWN	<u>\$</u>	VISIBILITY OBSTRUCTION (FOR CASE VEHICLE) (0) NONE (1) BUILDING (2) SIGN (3) VEGETATION (E.G. BUSHES, SHRUBS) (4) TREE (5) HILL OR CURVE IN ROAD (6) VEHICLE IN TRANSPORT (7) OTHER: (8) PARKED VEHICLE (9) UNKNOWN	<u>O</u> 39

GENERAL INFORMATION GI-2				
ENVIRONMENTAL CONDITIONS SPEED LIMIT (0) 5-45 km/h 5-25 mph (1) 46-55 30 (2) 56-60 35 (3) 61-70 40 (4) 71-79 45 (5) 80-85 50 (6) 86-90 55 (7) 91-105 60 (8) OVER 105 65 (9) UNKNOWN	40	MECHANICAL MALFUNCTION WAS THERE MENTION OF A MECHANICAL MALFUNCTION IN CASE VEHICLE (0) NO (1) YES (2) YES, DID NOT CONTRIBUTE TO ACCIDENT (9) UNKNOWN		
PRECIPITATION (0) NONE (1) RAIN (2) SNOW (3) HAIL (4) FREEZING RAIN/SLEET (7) OTHER: (9) UNKNOWN RATE OF PRECIPITATION (1) LIGHT/MIST (2) MODERATE (3) HEAVY (8) NOT APPLICABLE (9) UNKNOWN TEMPERATURE (0) BELOW -15° C BELOW 5° F (1) -15 TO -6 5 TO 22 (2) -5 TO -1 23 TO 31 (3) 0 TO 2 32 TO 36 (4) 3 TO 5 37 TO 41 (5) 6 TO 15 42 TO 59 (6) 16 TO 25 60 TO 77 (7) 26 TO 35 78 TO 95	6 41 8 42 4 3	THE FOLLOWING SECTION SHOULD BE FILLED OUT IF A MECHANICAL MALFUNCTION IS RECOGNIZED OR SUSPECTED. CIRCLE ITEMS INVOLVED. SUPPORT ANY ITEMS CIRCLED WITH COMMENTS. BRAKE SYSTEM DRIVER CONTROLS EXHAUST SYSTEM POWER TRAIN STEERING SYSTEM FUEL SYSTEM SUSPENSION SYSTEM VISIBILITY ITEMS ELECTRICAL SYSTEM TIRES THROTTLE CONTROLS UNKNOWN OTHER: COMMENTS:		
(8) OVER 35	44			

		GENERAL INFORMATION	GI-3
CRASH DETAILS CASE VEHICLE AND OBJECT (0) NO (1) YES (9) UNKNOWN	47	HIGHEST POLICE INJURY SEVERITY CODE IN CRASH (NOT JUST CASE VEHICLE) (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING INJURY (3) A - INCAPACITATING INJURY	
CASE VEHICLE ROLLOVER (0) NO ROLLOVER (1) YES, FIRST EVENT (2) YES, SUBSEQUENT EVENT (3) YES, SEQUENCE UNKNOWN (9) UNKNOWN	O 48	(4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN (9) UNKNOWN	<u>2</u>
CASE VEHICLE RAN OFF ROADWAY (BEFORE FIRST IMPACT) (0) NO (1) YES (9) UNKNOWN MOVING CASE VEHICLE AND CONTACTED MOVING VEHICLE (0) NO	8 49	DRIVER ALCOHOL INVOLVEMENT (CASE VEHICLE) (0) NONE (1) YES (9) UNKNOWN/NOT REPORTED/ NO DRIVER DRIVER ALCOHOL BAC (CASE VEHICLE) (80) NO TEST	<u>S</u>
(1) YES (9) UNKNOWN CASE VEHICLE AND CONTACTED STOPPED VEHICLE (0) NO (1) YES (9) UNKNOWN	50	(90) CHEMICAL TESTS, NO RESULTS (95) AUTOPSY, NO RESULTS (99) UNKNOWN WAS THERE MENTION OF DRIVER IMPAIRMENT FOR CASE VEHICLE? (0) NO (1) YES (9) UNKNOWN	57
STOPPED CASE VEHICLE AND CONTACTED VEHICLE (0) NO (1) YES (9) UNKNOWN TOTAL NUMBER	∂ 52	LIST IMPAIRMENTS MENTION	NED:
OF VEHICLES CONTACTED BY CASE VEHICLE IN CRASH (8) 8 OR MORE (9) UNKNOWN	53	POST - CRASH DETAIL MANNER CASE VEHICLE LEFT SCENE	
ANY FIRE IN THIS CRASH (NOT JUST CASE VEHICLE) (0) NO (1) YES (9) UNKNOWN	<u>D</u>	(1) DRIVEN(2) TOWED DUE TO DAMAGE(3) TOWED, NOT DUE TO DAMAGE(4) TOWED, REASON UNKNOWN(9) UNKNOWN	2 60

ACCIDENT DESCRIPTION: Case vehicle (A) was traveling west and Case Vehicle (A): 1998 Chevrolot Malibo


vehicle (B) was stopped at a stop sign facing nonth. OTHER VEHICLE (B): 1997 Chevrolot cisoo PU

As vehicle (B) began to enten the intersection, case THIRD VEHICLE (C):

vehicle (A) proceeded into the intersection and the left-front was struck by the frontof vehicle (B). Case vehicle (A) veened to the pight, went through a ditch,

on a lawn and sideswiped a utility pole.

NORTH



Duplicate columns 1-8 Module O V Format from the previous card.	0 4		OTHER VEHICLE	OV-1
MAKE: Chevaolet			CARGO:	
MODEL: Sienne CISOO 4x2, Exter	uded Ca	6 90		
VIN 2 G C E C 1 9	MX	YI	29	•
MANUFAC/BODY CODE 1 1 3	12	VEHIC	LE TYPE	
MAKE/MODEL CODE 29	02	(02) (03)	NGER VEHICLE LARGE LIMOUSINE PICKUP CAR	1 2 56
MODEL YEAR $\frac{1}{39}$ $\frac{9}{9}$	7	(20) (24) (25) (26)	UNKNOWN PASSENGER VEHICLE BODY SUB-MINI MINI SUB-COMPACT	
VEHICLE MASS (kg) Q D 1 8	<u>1</u> <u>48</u>	(28)	COMPACT INTERMEDIATE FULL	
IF SEPARATE REPORT WAS MADE, GIVE VEHICLE NUMBER	<u>0</u>	(14)	URPOSE PASSENGER VEHICLE SMALL UTILITY (WHEELBASE LESS THAN 107°, E.G. JEEP, BRONCO) LARGE UTILITY (WHEELBASE MORE THAN 107°, E.G. PANEL TRUCK, SUBURBAN)	
NUMBER OF OCCUPANTS (ENTER 9'S IF UNKNOWN)	51	(16) (17) (21) (22) (23)	PICKUP TRUCK WITH CANOPY/SHELL COVER PICKUP CAR WITH CANOPY/SHELL COVER MOTOR HOME PICKUP TRUCK WITH SLIDE-IN CAMPER PICKUP CAR WITH SLIDE-IN CAMPER	
TRAVELING SPEED (km/h)	5	(31)	CHASSIS-MOUNTED CAMPER	
(000) PARKED OR STOPPED (995) JUST STARTING UP (996) BACKING UP (997) SPEED NOT EXCESSIVE (BUT UNKNOWN) (998) SPEED EXCESSIVE (BUT UNKNOWN) (999) UNKNOWN	54	(13) (15) (16) (22) (30) (31)	VAN PICKUP TRUCK UNKNOWN LIGHT TRUCK LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN) PICKUP TRUCK WITH CANOPY/SHELL COVER PICKUP TRUCK WITH SLIDE-IN CAMPER UNKNOWN TRUCK TYPE CHASSIS-MOUNTED CAMPER DELIVERY VAN (WALK-IN)	
HIGHEST POLICE INJURY SEVERITY CODE FOR THIS VEHICLE (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING INJURY	55	(34) (35) (36) (37) (38) (38)	STRAIGHT TRUCK TRUCK-TRACTOR (BOBTAIL) CHASSIS-CAB UNKNOWN HEAVY TRUCK TRACTOR & SEMI-TRAILER (SEMI) TRUCK (OR SEMI) & FULL TRAILER(S)	
 (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO ACCIDENT (7) NON-FATAL INJURY SEVERITY UNKNOWN (8) UNOCCUPIED VEHICLE 		(41) S (42) I (43) T	UNKNOWN BUS TYPE SCHOOL BUS NTERCITY BUS (BETWEEN CITIES) FRANSIT BUS (INTRACITY) STREETCAR (ON TRACKS)	
(NOT APPLICABLE) (9) UNKNOWN		(68) 1 (69) L	FRAIN (CARS) LOCOMOTIVE (ENGINE, SWITCHER)	
			JNKNOWN	2
			BASE <i>(cm)</i> UNKNOWN	3 5 9 58 59 60

Duplicate columns 1-8 from the previous card. Module O V Format 0 2 9 10 11 12

OTHER VEHICLE

OV-2

ORIGINAL SPECIFICATIONS

Wheelbase

Front Overhang

0 9 0 cm

Curb Weight

Rear Overhang

 $\frac{1}{25} \frac{0}{3} \frac{6}{27} \text{ cm}$

Average Track Width
$$\frac{1}{13}$$
 $\frac{1}{15}$ cm

Overall Length $\frac{5}{16}$ $\frac{5}{18}$ cm


Undeformed End Width (UEW)


Engine Displacement


Overall Width (OAW) $\frac{1}{19}$ $\frac{9}{9}$ cm


Engine: # of Cylinders

VEHICLE DAMAGE









This vehicle WAS UNAVAILABLE

FRONTAL CRASH OVERLAP

Round up for .5. 98 = 98% or more Enter % overlap or "99" for missing or N/A. Direct Damage Length (DDL)

 $\frac{9}{35}$ $\frac{9}{9}$ cm

Front-End Overlap (Percent) = DDL

Vehicle Overlap (Percent) = <u>DDL + 1/2 (OAW - UEW)</u>

99%

Duplicate columns 1-8 Module V D Format (0 4		VEHICLE DESCRIPTION	VD-1
MAKE: Chevrolet MODEL: Malibu, 4-doon s	edan	<u> </u>	CARGO:	
VIN 1 6 1 N P 5	2	<u>M</u> <u>0</u>	<u>N</u> 6	29
MANUFAC/BODY CODE $\frac{1}{30}$ $\frac{13}{2}$	<u> 2</u> <u>8</u> 34	STOLE	N VEHICLE	
MAKE/MODEL CODE <u>0 1 3</u>	5 3			<u>8</u> 62
MODEL YEAR $\frac{1}{39}$ $\frac{q}{q}$	42			
VEHICLE MASS (kg) 0 0 1 3 8	48		STRUCTURE	2
ODOMETER (km) (ENTER 9'S IF UNKNOWN) (ENTER 8'S IF ELECTRONIC) 49	8 54	(2) U (3) II (4) B	ODY & FRAME INITIZED NTEGRAL-STUB FRAME ODY & PLATFORM FRAME	63
NUMBER OF OCCUPANTS (ENTER 9'S IF UNKNOWN)	56	(5) P (7) C	E.G. VW BUG) PARTIALLY UNITIZED DTHER: UNKNOWN	
TRAVELING SPEED (km/h) 9 9	<u> </u>			
(000) PARKED OR STOPPED (995) JUST STARTING UP (996) BACKING UP (997) SPEED NOT EXCESSIVE (BUT UNKNOWN) (998) SPEED EXCESSIVE (BUT UNKNOWN) (999) UNKNOWN	•	(0) N (1) A (2) M	MISSION IONE JUTOMATIC MANUAL INKNOWN	<u>)</u>
VEHICLE TYPE		LOCAT	ION OF TRANSMISSION	
PASSENGER VEHICLE (11) 2-DOOR HARDTOP (NO UPPER B-PILLAR) (12) 2-DOOR SEDAN OR COUPE	1 4	SELEC	ION OF TRANSMISSION TOR LEVER LOOR	7
(ANY UPPER B-PILLAR) (13) 4-DOOR HARDTOP (14) 4-DOOR SEDAN	60 61	(2) C (3) C	ONSOLE OLUMN OTHER:	65
(15) STATION WAGON (16) CONVERTIBLE (18) OTHER PASS. VEH. : (19) PASSENGER VEHICLE, TYPE UNKNOWN			NKNOWN ,	
MULTIPURPOSE PASSENGER VEHICLE (21) SMALL UTILITY (E.G. JEEP, SCOUT, BRONCO)		STEER	ING	
(22) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN) (23) VAN, SIZE UNKNOWN (24) VAN, SMALL (MINI) (25) VAN, LARGE (29) MPV, TYPE UNKNOWN (30) MOTOR HOME		(2) M	OWER IANUAL NKNOWN	66
TRUCK (31) PICKUP TRUCK, UNKNOWN (32) PICKUP TRUCK, SMALL (DOWNSIZED)		BRAKE:		,
(33) PICKUP TRUCK, LARGE (99) UNKNOWN		(2) M	OWER ANUAL NKNOWN	67
				1 1

		VEHICLE DESCRIPTION VD-2
TYPE OF BRAKES (1) DRUM, ALL WHEELS (2) DISC, FRONT WHEELS (3) DISC, ALL WHEELS (9) UNKNOWN	<u>2</u>	WHEELBASE <i>(cm)</i> (999) Unknown 272 76 77 78
BRAKE ANTI-LOCK DEVICE (0) NONE INSTALLED (1) TWO-WHEEL (2) FOUR-WHEEL (7) EQUIPPED, UNKNOWN WHEELS (9) UNKNOWN AIR CONDITIONING IN VEHICLE (0) NO (1) YES (8) NOT COLLECTED (9) UNKNOWN	2 69 8 70	PLASTIC ANTI-LACERATIVE INNER LAYER GLASS EQUIPPED (0) NONE (1) WINDSHIELD (2) WINDSHIELD AND SIDE (7) OTHER (9) UNKNOWN
TYPE OF DRIVE (1) REAR WHEEL (2) FRONT WHEEL (3) FOUR WHEEL (4) ALL WHEEL DRIVE (9) UNKNOWN DUAL REAR WHEELS (0) NO (1) YES (9) UNKNOWN ORIGINAL TYPE OF RESTRAINT SYSTEM (1) ACTIVE BELT (2) PASSIVE BELT (3) AIRBAG (4) KNEE BOLSTERS (7) OTHER: (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	2 71 0 72 3 73	FIELD INVESTIGATOR INSTRUCTIONS: 1. INDICATE CRUSHED AREAS BY OUTLINING NEW PERIMETER OF VEHICLE AND SHADING THE DAMAGED AREAS ON THE LARGE SKETCH ON PAGE VD-3. USE AS MANY SKETCHES AS NECESSARY TO COMPLETELY DESCRIBE THE DAMAGE. 2. ENTER THE DIMENSIONS ON THE SKETCH(ES) MEASURED TO THE POINT OF MAXIMUM PENETRATION BY THE OBJECT(S) CONTACTED. USE THE EXAMPLES BELOW AS A GUIDE. 3. ENTER THE THREE DIMENSIONS TO THE CENTER OF THE WHEELS (WHEELBASE, FRONT AND REAR OVERHANGS) ON BOTH SIDES OF THE CAR. 4. ADD OTHER DIMENSIONS AS NECESSARY TO COMPLETELY DESCRIBE THE DAMAGE. EXAMPLES:
EQUIPPED WITH ROLL BAR (0) NO (1) YES (9) UNKNOWN TYPE OF ROOF (0) NONE (1) SOLID (2) T-TOP CLOSED (3) T-TOP OPEN (4) SUN ROOF CLOSED (5) SUN ROOF OPEN (6) CONVERTIBLE CLOSED (7) CONVERTIBLE OPEN (8) OTHER: (9) UNKNOWN	74	FRONT OR REAR ROOF (REFERENCE TO TOP OF DOOR SILL OR WINDOW SILL)

Duplicate columns 1-8 from the previous card. Module V D Format 0 2

VEHICLE DESCRIPTION

VD-3

ORIGINAL SPECIFICATIONS

272 cm Wheelbase

Front Overhang

 $\frac{1}{2} \frac{0}{2} \frac{1}{24} \text{ cm}$

Curb Weight

1384 kg

Rear Overhang

 $\frac{1}{25}$ $\frac{1}{27}$ cm

Undeformed End Width (UEW) 1 9 cm


Overall Length

Engine Displacement

Overall Width (OAW) 1 7 6 cm

Engine: # of Cylinders

VEHICLE DAMAGE



FRONTAL CRASH OVERLAP

Round up for .5. 98 = 98% or more Enter % overlap or "99" for missing or N/A.

Direct Damage Length (DDL)

 $\frac{9}{35} = \frac{9}{9} = \frac{9}{37}$ cm

Front-End Overlap (Percent) = DDL UEW

99%

Vehicle Overlap (Percent) = <u>DDL + 1/2 (OAW - UEW)</u> OAW

99%

Duplicate columns 1-8 Module D // from the previous card.	A_Format <u>0 2</u>	DAMAGE DA-1
PRIMARY	CASE VEHICLE PRIMARY CDC	CONTACTED VEHICLE ASSOCIATED CDC
EVENT NUMBER	13	_
IMPACT SPEED (km/h)	<u>9</u> <u>9</u> <u>9</u> 16	$\frac{Q}{35} \frac{Q}{36} \frac{Q}{37}$
ESTIMATED BY	17	<u>/</u> 38
CRUSH (cm)		$\frac{9}{39} \frac{9}{40} \frac{9}{41}$
CDC #1	1 1 L F E W 2	99.0000.0
CDC #2	9 8.0000.0	99.000.0 49
Duplicate columns 1-8 Module D A from the previous card. 9 10	N Format 0 3 11 12	
SECONDARY	CASE VEHICLE SECONDARY CDC	CONTACTED VEHICLE ASSOCIATED CDC
EVENT NUMBER	2	
IMPACT SPEED (km/h)	9 9 9 16	$\frac{9}{35} \frac{9}{36} \frac{8}{37}$
ESTIMATED BY	17	<u>8</u> 38
CRUSH (cm)	$\frac{\mathcal{O}}{18} \frac{\mathcal{O}}{19} \frac{1}{20}$	$\frac{9}{39} \frac{9}{40} \frac{8}{41}$
CDC #1	1 2 R Y E 5 1 27	98.0000.0 98.0000.0 98.0000.0
CDC #2	9 8.0000.0	98.0000.0
Codes		
EVENT NUMBER	IMPACT SPEED ESTIMATOR	CRUSH
(8) NOT APPLICABLE (9) UNKNOWN	(1) INVESTIGATOR (2) DRIVER (3) POLICE	(998) NOT APPLICABLE (NO VEHICLE/DAMAGE) (999) UNKNOWN
IMPACT SPEED (998) NOT APPLICAB (999) UNKNOWN	(4) "CRASH" PROGRAM (5) OTHER COMPUTER PROGRAM	CDC (9800000) NOT APPLICABLE (9900000) UNKNOWN

Module <u>D</u> <u>A</u> Format <u>0</u> <u>1</u> 12 Duplicate columns 1-8 DAMAGE DA-2 from the previous card. MAXIMUM SHEET METAL CRUSH (999) UNKNOWN (cm) $\frac{0}{16} \frac{0}{1} \frac{1}{18}$ 0 0 0 FRONT RIGHT SIDE 0 10 $O_{19} O_{21}$ REAR LEFT SIDE 000 000 **ROOF OTHER** CHRONOLOGICAL SEQUENCE OF DAMAGE/INJURY PRODUCING CRASH EVENTS FOR CASE VEHICLE DO YOU KNOW THIS TABLE TO BE IN CHRONOLOGICAL ORDER? NOTE: IF CHRONOLOGICAL ORDER IS UNKNOWN, EVENT ORDER IS OPTIONAL. (0) NO (1) YES **EVENT** IMPACT CONFIGURATION **IMPACT LOCATION OBJECT/VEHICLE** NUMBER CONTACTED (1) ON ROADWAY (2) SHOULDER/MEDIAN/GORE FOR CODES, SEE TABLE FOR CODES, SEE TABLE (3) ON ROADSIDE ON PAGE DA-3. ON PAGE DA-4. (4) OUTSIDE ROADSIDE RIGHT-OF-WAY (5) OTHER (6) OFF ROADWAY, LOC. UNK. (9) UNKNOWN veH. (B) # 1 #2

#3

#4

#5

#6

#7

57

61

CODES FOR IMPACT CONFIGURATION

FRONT OF CASE VEHICLE

- (11) AND FRONT OF CONTACTED VEHICLE
- (13) AND SIDE OF CONTACTED VEHICLE
- (14) AND REAR OF CONTACTED VEHICLE
- (16) ENDSWIPED BY CONTACTED VEHICLE
- (17) AND OBJECT
- (19) AND UNKNOWN OTHER VEHICLE CONFIGURATION

LEFT SIDE OF CASE VEHICLE

- (21) AND FRONT OF CONTACTED VEHICLE (TYPE T)
- (22) AND FRONT OF CONTACTED VEHICLE (TYPE L)
- (23) AND SIDE OF CONTACTED VEHICLE (NOT SIDÉSWIPE)
- (24) AND REAR OF CONTACTED VEHICLE (TYPE T)
- (25) AND REAR OF CONTACTED VEHICLE (TYPE L)
- (26) SIDESWIPED BY CONTACTED VEHICLE
- (27) AND OBJECT
- (29) AND UNKNOWN OTHER VEHICLE CONFIGURATION

REAR OF CASE VEHICLE

- (31) AND FRONT OF CONTACTED VEHICLE
- (33) AND SIDE OF CONTACTED VEHICLE
- (34) AND REAR OF CONTACTED VEHICLE
- (36) ENDSWIPED BY CONTACTED VEHICLE
- (37) AND OBJECT
- (39) AND UNKNOWN OTHER VEHICLE CONFIGURATION

RIGHT SIDE OF CASE VEHICLE

- (41) AND <u>FRONT</u> OF CONTACTED VEHICLE (TYPE T) (42) AND <u>FRONT</u> OF CONTACTED VEHICLE (TYPE L)
- (43) AND SIDE OF CONTACTED VEHICLE (NOT SIDESWIPE)
- (44) AND REAR OF CONTACTED VEHICLE (TYPE T)
- (45) AND REAR OF CONTACTED VEHICLE (TYPE L)
- (46) SIDESWIPED BY CONTACTED VEHICLE
- (47) AND OBJECT
- (49) AND UNKNOWN OTHER VEHICLE CONFIGURATION

OTHER

- (57) VEHICLE TO OBJECT
- (58) VEHICLE TO VEHICLE
- (59) VEHICLE TO VEHICLE, CONFIGURATION UNKNOWN

ROLLOVER

- (61) LESS THAN 360°
- (62) 360° OR MORE
- (69) DETAILS UNKNOWN

UNKNOWN

(99) IMPACT TYPE UNKNOWN

CODES FOR VEHICLE/OBJECT CONTACTED

VEHICLE/OBJECT GROUPS

- NO OBJECT
- (01) (39) PASSENGER VEHICLE & TRUCK
- (40) (69) OTHER VEHICLE
- (70) (76) PEDESTRIAN & ON-ROADWAY OBJECT
- (77) (97) OFF-ROADWAY OBJECT
- (98)OTHER (DESCRIBE)
- (99)UNKNOWN

PASSENGER VEHICLE

- (02) LARGE
- (03) LIMOUSINE
- (17) PICKUP
- (20) UNKNOWN PASSENGER VEHICLE BODY
- (24) SUB-MINI
- (25) MINI
- (26) SUB-COMPACT
- (27) COMPACT
- (28) INTERMEDIATE
- (29) FULL

SIZE

WHEELBASE

SUB-MINI	< 2286 mm (< 90")
MINI	2286 - 2412 mm (90° - 94.9°)
SUB-COMPACT	2413 - 2539 mm (95" - 99.9")
COMPACT	2540 - 2666 mm (100" - 104.9")
INTERMEDIATE	2667 - 2793 mm (105" - 109.9")
FULL	2794 - 2920 mm (110" - 114.9")
LARGE	2921 - 3174 mm (115" - 124.9")
LIMOUSINE	> 3175 mm (> 125")

MULTIPURPOSE PASSENGER VEHICLE

- (11) SMALL VAN (MINI)
- (12) PICKUP
- (14) SMALL UTILITY (WHEELBASE LESS THAN 107". E.G. JEEP, BRONCO)
- (15) LARGE UTILITY (WHEELBASE MORE THAN 107". E.G. PANEL TRUCK, SUBURBAN)
- (16) PICKUP TRUCK WITH CANOPY/SHELL COVER
- (17) PICKUP CAR WITH CANOPY/SHELL COVER
- (21) MOTOR HOME
- (22) PICKUP TRUCK WITH SLIDE-IN CAMPER
- (23) PICKUP CAR WITH SLIDE-IN CAMPER
- (31) CHASSIS-MOUNTED CAMPER

TRUCK

- (11) SMALL VAN (E.G. ECONOLINE)
- (12) PICKUP TRUCK
- (13) UNKNOWN LIGHT TRUCK
- (15) LARGE UTILITY (E.G. PANEL TRUCK, SUBURBAN)
 (16) PICKUP TRUCK WITH CANOPY/SHELL COVER
- (22) PICKUP TRUCK WITH SLIDE-IN CAMPER
- (30) UNKNOWN TRUCK TYPE
- (31) CHASSIS-MOUNTED CAMPER (33) DELIVERY VAN (WALK-IN)

- (34) STRAIGHT TRUCK (35) TRUCK-TRACTOR (BOBTAIL)
- (36) CHASSIS-CAB
- (37) UNKNOWN HEAVY TRUCK
- (38) TRACTOR & SEMI-TRAILER (SEMI)
- (39) TRUCK (OR SEMI) & FULL TRAILER(S)

Bus

- (40) UNKNOWN BUS TYPE
- (41) SCHOOL BUS
- (42) INTERCITY BUS (BETWEEN CITIES)
- (43) TRANSIT BUS (INTRACITY)
- (44) STREETCAR (ON TRACKS)

MOTORCYCLE

- (50) UNKNOWN MOTORCYCLE TYPE
- (51) 1 75 cc (52) 76 125 cc
- (53) 126 250 cc
- (54) 251 500 cc
- (55) 501 750 cc
- (56) 751 cc +
- (57) 3-WHEELS (OR WITH SIDECAR)

SPECIAL PURPOSE VEHICLE

- (60) UNKNOWN/OTHER SPECIAL VEHICLE (DESCRIBE)
- (61) SNOWMOBILE
- (62) ATV (ALL TERRAIN VEHICLE) (63) AMPHIBIOUS VEHICLE
- (64) FARM VEHICLE
- (65) CONSTRUCTION VEHICLE
- (66) TRAILER, PRIVATE (CAMPER)
- (67) TRAILER, COMMERCIAL (CARGO)
- (68) TRAIN (CARS)
- (69) LOCOMOTIVE (ENGINE, SWITCHER)

OBJECT

- (70) PEDESTRIAN
- (71) BICYCLIST, OTHER PEDALCYCLIST
- (72) PEDESTRIAN CONVEYANCE (E.G. PERSON RIDING ANIMAL, CART)
- (73) LARGE ANIMAL
- (74) FALLEN OBJECT (E.G. OBJECT DISLODGED FROM OTHER VEHICLE, FALLEN TREE. ROCKS)
- (75) ROCKS
- (76) CONSTRUCTION EQUIPMENT (EXCLUDING (65))
- (77) SIGN POST, UTILITY POLE, TREE
- (78) DITCH
- (79) EMBANKMENT, SNOWBANK, RR TRACKS RR X
- (80) GROUND (ROLLOVER ONLY)
- (81) CURB (DAMAGE PRODUCING IMPACTS ONLY)
- (82) CULVERT
- (83) FENCE
- (84) HYDRANT, SHORT POST, STUMP
- (85) SMALL POST/TREE, RURAL MAIL BOX, MILE MARKER, DELINEATOR
- (86) BUILDING
- (87) PIER, PILLAR, BRIDGE SUPPORT (88) ABUTMENT, RETAINING WALL
- (89) BRIDGE RAIL
- (90) GUARD RAIL, LEADING SECTION
- (91) GUARD RAIL, MIDDLE OR UNKNOWN (92) GUARD RAIL, TRAILING SECTION
- (93) GUARD POST (TIMBER, METAL, CONCRETE) (94) CABLE, FENCE BARRIER
- (95) CONCRETE BARRIER (MEDIAN)
- (96) IMPACT ATTENUATOR
- (97) BREAKAWAY FEATURES

Duplicate columns 1-8 Module C from the previous card. 9 1	R Format 0 1 10 11 12		SH RECONSTRUC or AV	CTION CR-1
	CASE VEHICLE F	PRIMARY IMPACT	CASE VEHICLE SE	ECONDARY IMPACT
	CASE VEHICLE	CONTACTED VEHICLE	CASE VEHICLE	CONTACTED VEHICLE
EVENT NUMBER	13	Vel·B	<u>Z</u>	utility pole
ΔV (km/h) TOTAL	14 15 16	9	48 49 50	8
LONGITUDINAL*	9	35 38	51 - 54	<u>8</u> — 72
LATERAL*	9	9	9—	8-
*NOTE: THESE ΔV COMPONENTS MUST INCLUDE SIGN.	21 24	39 42	55 58	73 76
EXAMPLES: 10 km/h = ± <u>0</u> 1 <u>0</u> -7 km/h = <u>:</u> <u>0</u> <u>0</u> <u>7</u>				
ENERGY DISSIPATED BY CRUSH (kj)	9 28	<u>q</u>	9 ————————————————————————————————————	<u>8</u> 80
RECONSTRUCTION			14.1	
(01) RECONSTRUCTED, UNKNOWN CONFIDENCE LEVEL	12		08	
(21) RECONSTRUCTED, LOW CONFIDENCE LEVEL (22) RECONSTRUCTED, MODERATE CONFIDENCE LEVEL (23) RECONSTRUCTED, HIGH CONFIDENCE LEVEL	29 30		63 64	
NOT RECONSTRUCTED BECAUSE				
(02) INSUFFICIENT DATA (03) EXCESSIVE UNDERRIDE/ OVERRIDE (04) ROLLOVER (05) VAULTING (06) OTHER TRAVEL IN MORE THAN ONE PLANE (07) NON-HORIZONTAL FORCE (08) SIDESWIPE-TYPE DAMAGE (09) YIELDING OBJECT (10) OTHER: (11) AT LEAST ONE VEHICLE BEYOND SCOPE (12) OTHER VEHICLE NOT INSPECTED				
MODE				
(1) CDC ONLY (2) CDC & DETAILED DAMAGE (3) TRAJECTORY & CDC (4) TRAJECTORY & CDC & DETAILED DAMAGE (5) NOT RECONSTRUCTED	31		<u>5</u>	
COMPUTER PROGRAM SPECIFY:				

CR-2

	· · · · · · · · · · · · · · · · · · ·	f	or EBS	
	CASE VEHICLE	PRIMARY IMPACT	CASE VEHICLE SI	ECONDARY IMPACT
	CASE VEHICLE	CONTACTED VEHICLE	CASE VEHICLE	CONTACTED VEHICLE
EVENT NUMBER	13		<u>Z</u>	polt
EBS (km/h) TOTAL	0 1/ 15 16	9	48 49 50	8
LONGITUDINAL*	$\frac{-0.15}{17}$	$\frac{9}{35} = {38}$	9	8
LATERAL* NOTE: THESE EBS COMPONENTS	+ 0 0 5 21	9	9	8
MUST INCLUDE SIGN.				·
EXAMPLES: 10 km/h = ± <u>0</u> 1 <u>0</u> -7 km/h = ± <u>0</u> <u>0</u> Z				
ENERGY DISSIPATED BY CRUSH (kj)	O O 1 6 25	9	9	8
RECONSTRUCTION				
(01) RECONSTRUCTED, UNKNOWN CONFIDENCE LEVEL	21		08	
(21) RECONSTRUCTED, LOW CONFIDENCE LEVEL (22) RECONSTRUCTED, MODERATE CONFIDENCE LEVEL (23) RECONSTRUCTED, HIGH CONFIDENCE LEVEL	29 30		63 64	
NOT RECONSTRUCTED BECAUSE				
(02) INSUFFICIENT DATA (03) EXCESSIVE UNDERRIDE/ OVERRIDE (04) ROLLOVER (05) VAULTING (06) OTHER TRAVEL IN MORE THAN ONE PLANE (07) NON-HORIZONTAL FORCE (08) SIDESWIPE-TYPE DAMAGE (09) YIELDING OBJECT (10) OTHER: (11) AT LEAST ONE VEHICLE BEYOND SCOPE (12) OTHER VEHICLE NOT				
INSPECTED MODE				
(1) CDC ONLY (2) CDC & DETAILED DAMAGE (3) TRAJECTORY & CDC (4) TRAJECTORY & CDC & DETAILED DAMAGE (5) NOT RECONSTRUCTED COMPUTER PROGRAM SPECIFY:	2 31		<u>5</u>	

Duplicate columns 1-8 from the previous card.

Module <u>C</u> <u>R</u> Format <u>0</u> <u>3</u>

CRASH RECONSTRUCTION

CR-3

NOTES:

- 1. ENTER CRASH RECONSTRUCTION DAMAGE MEASUREMENTS IN CENTIMETERS.
- 2. MEASURE C $_{\rm 1}$ TO C $_{\rm 6}$ FROM DRIVER TO PASSENGER SIDE IN FRONT OR REAR IMPACTS, REAR TO FRONT IN SIDE IMPACTS.


CASE VEHICLE

LOCATOR

- 3. D IS POSITIVE IF MEASURED TO A POINT FORWARD OF OR TO THE RIGHT OF THE CG.
- 4. USE THE CENTER OF THE WHEELBASE AS THE CG.

Locate the end of the damage with respect to the vehicle longitudinal center line, or an undamaged axle for side impacts.

Specific Impact No.	Location of Direct Damage	Location of Field L
/	Begin LFBC, 201cm to nema	Begin LFBC, 230 cm to Kean
2	126 cm REAR of RFBC	Sam



DL ____

UDL

PLANE:

- (1) Bumper
- (2) Above Bumper
- (3) Sill
- (4) Above Sill
- (5) Other_
- (9) Unknown

CRUSH PROFILE IN CENTIMETERS

	NOTE: Each	line in the tal	ole below is a	separate rec	ord (card).		plicate col	umns 1 - 1	2 for each	complete	d line.
Specific Impact Number	Plane of Impact C-Measur.	Direct Length (DDL)	Damage Max Crush	Field L	C ₁	C ₂	C ₃	C ₄	C ₅	C ₆	±D
- 1	4	201	10	230	0	10	8	5	7	10	+115
		•									
1	Ч	201	010	230	000	010	008	005	007	010	+ 115
13	14 4	15 16 17	18 19 20	179	24 25 26	27 28 29	30 31 32	33 34 35			
2	4	179	001	179	000	000	000	000	000	000	+026

Duplicate columns 1-8 from the previous card.

Module <u>C</u> <u>R</u> Format <u>0</u> <u>4</u>

CRASH RECONSTRUCTION

CR-4

NOTES:

- 1. ENTER CRASH RECONSTRUCTION DAMAGE MEASUREMENTS IN CENTIMETERS.
- 2. MEASURE C $_{\rm 1}$ TO C $_{\rm 6}$ FROM DRIVER TO PASSENGER SIDE IN FRONT OR REAR IMPACTS, REAR TO FRONT IN SIDE IMPACTS.


OTHER VEHICLE

LOCATOR

- 3. D IS POSITIVE IF MEASURED TO A POINT FORWARD OF OR TO THE RIGHT OF THE CG.
- 4. USE THE CENTER OF THE WHEELBASE AS THE CG.

Locate the end of the damage with respect to the vehicle longitudinal center line, or an undamaged axle for side impacts.

Specific Impact No.	Location of Direct Damage	Location of Field L



DL _____

UDL

PLANE:

- (1) Bumper
- (2) Above Bumper
- (3) Sill
- (4) Above Sill
- (5) Other _
- (9) Unknown

CRUSH PROFILE IN CENTIMETERS

NOTE: Each line in the table below is a separate record (card).

Duplicate columns 1 - 12 for each completed line.

				ooparate ree	3. G (GG: G).		piloato con		<u> </u>	our proto	a mic.
Specific	Plane	Direct	Damage			1					
Impact	of Impact	Length	Max	Field	C ₁	C ₂	C ₃	C ₄	C ₅	C ₆	±D
Number	C-Measur.	Length (DDL)	Crush		-	-2	_ ~3	-4	J 25	~6	
Number	O-Measur.	(DDL)	Orusii								
1	9	999	999	999	999	999	999	999	999	994	+999
13	14	15 16 17	18 19 20	21 22 23	24 25 26	27 28 29			36 37 38		42 43 44 4
2											

Duplicate columns 1-8 Module W T Format 0 from the previous card.	WHEELS AND TIRES WT
WHEELSDAMAGED (0) NO (1) YES (9) UNKNOWN RR LR	SIZE (NOT DOT CODE. IF UNKNOWN, USE 9'S) LF
TIRE TREAD TYPE LF (1) REGULAR (2) SNOW RF (3) SLICKS (4) ALL WEATHER (MS) (7) OTHER: RR (9) UNKNOWN LR	4 4 4 4 20
CARCASS CONSTRUCTION LF (1) BIAS (2) BELTED BIAS RF (3) RADIAL (4) ELLIPTICAL (5) HI PRESSURE SPARE (6) SPACE SAVER SPARE (7) OTHER: (9) UNKNOWN LR	2 3 3 3 24
IF VEHICLE IS EQUIPPED WITH DUAL WHEELS, COMPLETE FOR OUTER WHEELS AND MAKE NOTES ON INNER WHEELS. NOTES:	

Duplicate columns 1-8 Module F T For from the previous card.	rmat <u>0 1</u>	FUEL AND FUEL TANKS	FUEL AND FUEL TANKS FT-1		
TYPE OF PROPULSIVE FUEL (1) GASOLINE (2) DIESEL OIL (3) LPG (4) ELECTRIC (7) OTHER: (9) UNKNOWN	13	AUXILIARY TANK TYPE (1) OEM TANK (2) AFTER MARKET TANK (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN	21		
MAIN TANK LOCATION	1 37	AUXILIARY TANK LOCATION	8 8 8 22 24		
MAIN FILLER CAP LOCATION	322 17 19	AUXILIARY FILLER CAP LOCATION	8 8 8 25 27		
MAIN TANK MATERIAL	1 20	AUXILIARY TANK MATERIAL	<u>8</u> 28		
TANK A	AND FILLER CA	AP LOCATION CODES			
FIRS	T DIGIT (LONGITI	UDINAL)			
(2 (3 (4 (4	1) BEHIND KICK-1 2) IN KICK-UP 3) BETWEEN KIC 4) FORWARD OF 3) NOT APPLICAE 9) UNKNOWN	K-UP & COWL			
SECO	OND DIGIT (LATE	RAL)			
(2) LEFT OF FRAME) WITHIN FRAME B) RIGHT OF FRA	OR CENTERED			

- (3) RIGHT OF FRAME(4) DUAL, RIGHT & LEFT TANKS(8) NOT APPLICABLE (NOT EQUIPPED)(9) UNKNOWN

THIRD DIGIT (VERTICAL)

- (1) BELOW FRAME (2) WITHIN FRAME OR CENTERED
- (3) ABOVE FRAME
 (8) NOT APPLICABLE (NOT EQUIPPED)
 (9) UNKNOWN

TANK MATERIAL CODES

- (1) STEEL

- (1) STEEL
 (2) ALUMINUM
 (3) PLASTIC
 (7) OTHER
 (8) NOT APPLICABLE (NOT EQUIPPED)
 (9) UNKNOWN

Duplicate	columns 1-8
from the c	revious card.

Module	<u>F</u>	_L_	Format 0	_1
	9	10	11	12

FUEL LEAKAGE

FL-1

DID FUEL LEAKAGE RESULT FROM A CRASH EVENT

(0) NO KNOWN LEAKAGE SKIP PAGE.

(1) YES <u>COMPLETE</u> PAGE.



	į	11	111	IV	V	
LEAK NUMBER	LEAKING COMPONENT	COMPONENT SOURCE	TYPE OF DAMAGE	SEVERITY OF DAMAGE	LOCATION OF LEAK	EVENT NUMBER
#1	14 15					21
#2	22 23					29
#3	30 31					37
#4	38 39					
#5	46 47			 -		53

LEAKING COMPONENT

TANK AREA

- (11) MAIN FUEL TANK (INCLUDING VAPOR RECOVERY DOME)
- (12) AUXILIARY FUEL TANK
- (13) MAIN TANK FILLER TUBE
- (14) MAIN TANK CAP (GAS CAP)
- (15) AUXILIARY TANK FILLER TUBE
- (16) AUXILIARY TANK CAP (GAS CAP)
- (19) TANK AREA, DETAILS UNKNOWN

DELIVERY SYSTEM

- (21) FUEL FEED LINE (MAIN TANK TO FUEL PUMP)
- (22) FUEL FEED LINE (AUXILIARY TANK TO FUEL PUMP)
- (23) FUEL RETURN LINE (FUEL PUMP TO TANK)
- (24) INLINE FUEL FILTER
- (25) FUEL LINE (PUMP TO CARBURETOR OR INJECTOR PUMP)
- (26) CARBURETOR TO INJECTOR PUMP
- (27) FUEL PUMP
- (29) DELIVERY SYSTEM, DETAILS UNKNOWN

EVAPORATIVE EMISSION CONTROL SYSTEM

- (31) ATMOSPHERIC VENT PIPE (NON-EEC EQUIPPED)
- (32) EEC PIPE (VAPOR CANISTER TO CARBURETOR)

EEC SYSTEM (CONTINUED)

- (33) VAPOR RECOVERY HOSES (CANISTER TO CARBURETOR)
- (34) LIQUID-VAPOR SEPARATOR (UNLESS PART OF TANK)
- (35) CANISTER
- (39) EEC SYSTEM, DETAILS UNKNOWN
- (49) ENGINE COMPARTMENT, COMPONENT UNKNOWN
- (99) COMPONENT UNKNOWN

II COMPONENT SOURCE

- (1) OEM
- (2) AFTER MARKET
- (9) UNKNOWN

III TYPE OF DAMAGE

- (1) DENTED/CRUSHED
- (2) PUNCTURED
- (3) RUPTURED
- (4) SEVERED/GROSS TEARS
- (5) DISCONNECTED/DEFEATED
- (9) UNKNOWN

IV SEVERITY OF DAMAGE

- (1) MINOR
- (2) MODERATE
- (3) SEVERE
- (4) DISCONNECTED/DEFEATED
- (9) UNKNOWN

V LOCATION OF LEAK

FIRST DIGIT (LONGITUDINAL LOCATION)

- (1) F, FORWARD OF COWL
- (2) P, BETWEEN COWL & REAR BULKHEAD
- (3) B, BEHIND REAR BULKHEAD
- (4) Y, F, & P
- (5) Z, P, & B
- (6) D, DISTRIBUTED (F, P & B)
- (9) UNKNOWN
- SECOND DIGIT (LATERAL LOCATION)
- (1) L, LEFT
- (2) C, CENTER
- (3) R, RIGHT
- (4) Y, LEFT CENTER (L & C)
- (5) Z, RIGHT CENTER (R & C)
- (6) D, DISTRIBUTED (F, P & B)
- (9) UNKNOWN

Duplicate columns 1-8 Module F R Format 0 from the previous card. 9 10 11		FIRE	FR-1
WAS THERE FIRE IN (0) NO <u>SKIP</u> PAG (1) YES <u>COMPLE</u>	ĜE.	CASE VEHICLE?	
DID FIRE START IN CASE VEHICLE? (0) NO (1) YES (9) UNKNOWN	14	SEVERITY OF FIRE DAMAGE (1) MINOR (2) MODERATE (3) SEVERE (9) UNKNOWN	16
FLAME PROPOGATION RATE (1) RAPID/EXPLOSIVE (2) SLOW/MODERATE (9) UNKNOWN	15	DID AN INJURY TO CASE VEHICLE OCCUPANT RESULT FROM FIRE IN OR ON CASE VEHICLE? (0) NO (1) YES (9) UNKNOWN	17

PROVIDE NOTES IF FIRE OCCURRED.

Duplicate columns 1-8 Module E D For from the previous card.	mat <u>0 1</u>	EXTERIOR DAMAGE	ED-1
	11 12		
HOOD PERFORMANCE		STEERING COL FLEXIBLE COUPLING	
FOR THE FOLLOWING, USE CODES:		FLEXIBLE COUPLING TYPE	
(0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN		(0) NONE (1) FLEXIBLE MATERIAL (2) POT (3) SINGLE U-JOINT (4) DOUBLE U-JOINT (5) FLEXIBLE CABLE (6) COMBINATION OF ABOVE (CIRCLE EACH)	9 26
HOOD LATCH(ES)RELEA	SED $\frac{\mathcal{O}}{13}$ SED $\frac{\mathcal{O}}{14}$	(7) OTHER: (8) EQUIPPED, TYPE UNKNOWN (9) UNKNOWN, IF EQUIPPED	
-DAMAG	SED O		
-JAMME	ED 14	COUPLINGDAMAGED (USE CODES FROM HOOD PERFORMANCE) -SEPARATED (COMPLETE)	
HOOD HINGESLEFT, DAMAG	ATED 17	(00,11, 22, 12)	20
-LEFT, SEPARA (COMPL	TED 17		
-RIGHT, DAMAG	ED <u>0</u> 18 8	ENG COMPART TELESCOPING UNIT	
-RIGHT, SEPARA (COMPL		(00) NONE INSTALLED (01) - (07) SEE UNITS ON PAGE ED-2	8 8
HOOD REMAINED ON VEHICLE	1 20	(88) NOT COLLECTED (97) OTHER: (98) EQUIPPED, TYPE UNKNOWN (99) UNKNOWN IF EQUIPPED	29 30
REAR EDGE OF HOODELEVAT	21	ORIGINAL LENGTH (mm)	
-CONTACTED WINDSHI		F (OR H):	
-PENETRATED WINDSHII	ELD 22 ELD 23	TELESCOPED LENGTH (mm) G:	
HOOD LATCH LOCATION			
(1) FRONT OF VEHICLE(2) COWL AREA(3) SIDE(8) NOT APPLICABLE(9) UNKNOWN	24	DIFFERENCE (mm) F (OR H) - G (IF LESS THAN 15mm, ENTER *000*.)	
ENGINE OR TRANSMISSION MOUNT SEPARATION (COMPLETE) (0) NO (1) YES (9) UNKNOWN	∂ 25	(888) NOT COLLECTED (991) NOT MEASURED/NO COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8

?	
N ON TION TION	
OR) -FRONT	0
-REAR	O 44
OR)	1 45
-REAR	<u>Ø</u>
	OR) -FRONT


		EXTERIOR DAMAGE	ED-3
		OTHER REAR DAMAGE	
REAR DOOR TYPE	0	WAS PARTITION TO LUGGAGE AREA DAMAGED DURING COLLISION? (0) NO	c
 (0) NO DOOR (INCLUDES PICKUPS) (1) HATCHBACK (2) ONE-WAY TAILGATE (3) TWO-WAY TAILGATE (4) CLAMSHELL/DISAPPEARING TAILGATE 	47	(1) YES (8) NOT APPLICABLE (9) UNKNOWN	50
(5) SINGLE DOOR (6) DOUBLE DOOR (9) UNKNOWN		SPARE TIRE	
Hatchback		 (0) NO SPARE TIRE (1) NOT ATTACHED BEFORE COLLISION (2) ATTACHED, NOT SEPARATED IN COLLISION (3) ATTACHED, SEPARATED DUE TO COLLISION (8) NOT COLLECTED 	51
One-way —		(9) UNKNOWN	
Two-way or or		TRAILER HITCH TYPE	
Clamshell		(0) NO HITCH BALL-AND-SOCKET TYPES	<u>C</u>
Single door		 (1) TEMPORARY FRAMEWORK (E.G. RENTAL CLAMP-ON) (2) BUMPER-MOUNT ONLY (E.G. LIGHT TRUCK) (3) BUMPER-AND-FRAME (BUT NON-EQUALIZING) 	
Double door		(4) LOAD EQUÁLIZING OTHER TYPES	
HOW DID DOOR OPEN DURING COLLISION?		 (5) RING-AND-PINTLE (6) FIFTH-WHEEL (INCL. P/U) (7) OTHER (E.G. CLEVIS-AND-PIN) 	
(0) DOOR DID NOT OPEN OPENED BECAUSE OF	8	(8) EQUIPPED, TYPE UNKNOWN (9) UNKNOWN IF EQUIPPED	
 (1) HINGE AREA SEPARATION (2) DOOR-LATCH SEPARATION (3) LATCH-STRIKER SEPARATION (4) STRIKER-PILLAR SEPARATION (5) BODY DISTORTION 		TRAILER TYPE (AT TIME OF COLLISION) (0) NO TRAILER	0
(6) COMBINATION OF ABOVE (CIRCLE EACH) (7) OPENED, REASON UNKNOWN		(1) TRAVEL-TRAILER/CAMPER (2) MOBILE HOME (3) BOAT/SNOWMOBILE/ATV TRAILER	53
(8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN		(4) UTILITY TRAILER (5) TOWED CAR (7) OTHER:	
DOOR JAMMED CLOSED	8	(8) TRAILER, TYPE UNKNOWN (9) UNKNOWN	
(0) NO (1) YES (8) NOT APPLICABLE (NO DOOR) (9) UNKNOWN	49		

		EXTERIOR DAMAGE	ED-4
RIGHT-SIDE BODY MOUNT DID BODY MOUNT SEPARATE? (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	8 54	RIGHT DOORS HOW DID DOORS OPEN DURING COLLISION? USE CODES:	
RIGHT PILLARS PILLARS SEPARATED COMPLETELY - USE CODES: (0) NO (1) YES (4) NO SEPARATION, BUT DAMAGED (8) NOT APPLICABLE (NOT EQUIPPED) (9) UNKNOWN		(00) DOOR DID NOT OPEN OPENED BECAUSE OF (01) HINGE AREA SEPARATION (02) DOOR-LATCH SEPARATION (03) LATCH-STRIKER SEPARATION (04) STRIKER-PILLAR SEPARATION (05) BODY DISTORTION (06) COMBINATION OF ABOVE (CIRCLE EACH) (07) OPENED, REASON UNKNOWN (11) VAN RIGHT-REAR DOOR OPENED (ANY MECHANISM)	
-A-PILLAR, UPPER	⊘ 55	(98) NOT APPLICABLE (NO DOOR) (99) UNKNOWN -FRONT	00
LOWER	<u>O</u> 56	-REAR	63 64 O O 65 66
-B-PILLAR, UPPER LOWER	<u>57</u>	DOORS JAMMED CLOSED- USE CODES:	
-C-PILLAR, UPPER	<u>D</u>	(0) NO (1) YES (8) NOT APPLICABLE <i>(NO DOOR)</i> (9) UNKNOWN	0
LOWER	<u>Q</u>	-FRONT -REAR	67
-D-PILLAR, UPPER	61	VAN REAR DOOR TYPE	33
LOWER	62	(0) VAN, NO REAR DOOR (1) TRACK (SLIDING) - RIGHT SIDE (2) SINGLE-HINGED - RIGHT SIDE (3) DOUBLE-HINGED - RIGHT SIDE (4) TRACK (SLIDING) - RIGHT & LEFT SIDE (5) SINGLE-HINGED - RIGHT & LEFT SIDE (6) DOUBLE-HINGED - RIGHT & LEFT SIDE (7) TRACK AND HINGED COMBINATION (8) NOT APPLICABLE (NOT A VAN) (9) UNKNOWN	

Duplicate columns 1-8 Module S C Format 0 from the previous card.	1 12	STEERING WHEEL AND COLUMN	SC-1
STEERING WHEEL		STEERING WHEEL POSITION AT TIME OF COLLISION	
STEERING WHEEL RIM DAMAGE (0) NONE (1) DEFORMED SLIGHTLY (2) SEVERELY BENT (3) BROKEN (9) UNKNOWN	13	IN WHAT O'CLOCK POSITION WAS THE NORMAL TOP OF THE WHEEL POINTED WHEN THE COLLISION OCCURRED? EXAMPLES O'CLOCK = 1 2 O'CLOCK = 0 2	
NUMBER OF STEERING WHEEL SPOKES (9) UNKNOWN	4	(NORMAL STRAIGHT AHEAD) O'GLOCK - 12	
STEERING WHL SPOKE DAMAGE (0) NONE (1) DEFORMED SLIGHTLY (2) SEVERELY BENT (3) BROKEN (9) UNKNOWN	15	STEERING WHEEL ENERGY ABSORBING DEVICE (1) EXAMPLES: BARRACUDA, 70-74 CHALLENGER, 70-74 CAPRI, 71-77	
STEERING COLUMN OPTIONS		(2) EXAMPLES: OMNI, 78 - HORIZON, 78 -	
TILT FEATURE (0) NOT EQUIPPED (1) YES, EQUIPPED, UNK POSITION (2) UP (3) MIDDLE (4) LOWER (9) UNKNOWN IF EQUIPPED	<u>3</u>	TYPE OF DEVICE (0) NONE (1) CONVOLUTED OR MESH CYLINDER (2) DEEP DISH STEERING WHEEL (7) OTHER: (8) NOT COLLECTED (9) UNKNOWN IF EQUIPPED	8 19
SWING-AWAY FEATURE (0) NOT EQUIPPED (1) YES, EQUIPPED (9) UNKNOWN IF EQUIPPED	<u></u>	ORIGINAL DIMENSION (mm) A: DAMAGE DIMENSION (mm) B:	
TELESCOPING FEATURE (0) NOT EQUIPPED (1) YES, EQUIPPED (9) UNKNOWN IF EQUIPPED	<u></u> 18	DIFFERENCE (mm) A - B (888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO MEASURE (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8

		STEERING WHEEL AND COLUMN	SC-2
STEERING COLUMN ENERGY ABSORBING DEVICE TYPE OF DEVICE * (IF 27 OR 28) (00) NOT EQUIPPED (88) NOT COLLECTED (99) UNKNOWN ORIGINAL LENGTH (mm)	8 8 23 24	STEERING WHEEL (CONTINUED) STEERING WHEEL HUB DAMAGE (0) NONE (1) OCCUPANT CONTACT (2) AIRBAG (3) OTHER (9) UNKNOWN	<u>⊘</u> 33
C: COMPRESSED LENGTH (mm) D: BRACKET DEFLECTION (IF CODE 36, 46, OR 49 ABOVE) OR COMPRESSION (OR EXTRUSION) (mm) C - D (OR E) (TOLERANCE: ±10) (888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT COMPRESSION (992) COMPRESSED, AMOUNT UNKNOWN (993) DEVICE EXTENDED (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN * (ADD A & B FOR TOTAL COMPRESSION) SHEAR CAPSULE SEPARATION (mm) S (USE AVG. OF LEFT & RIGHT CAPSULES.) LT:	8 8 8 27		
RT: (888) NOT COLLECTED (991) NOT MEASURED/NO APPARENT SEPARATION (992) SEPARATED, AMOUNT UNKNOWN (997) UNABLE TO BE MEASURED (998) NOT APPLICABLE (NOT EQUIPPED) (999) UNKNOWN	8 8 8		
COLUMN VERTICAL ROTATION (0) NO APPARENT ROTATION (1) UPWARD APPARENT ROTATION (2) DOWNWARD APPARENT ROTATION (9) UNKNOWN	<u>O</u> 31		
COLUMN LATERAL ROTATION (0) NO APPARENT ROTATION (1) LEFT APPARENT ROTATION (2) RIGHT APPARENT ROTATION (9) UNKNOWN	$\frac{\mathcal{O}}{z}$		

					Intrusio	N IT-1
					(All Measurements Are in Centimeters)	
Location Intrusio	of on	Intruded	l Component	Compai Valu	ison Intruded e — Value = Intrusion	Dominant Crush Direction
					- =	
					_ =	
					= =	
					_ =	
					_ =	
					- =	
					_ =	
					_ =	
					_ =	
					_ =	
					=	
					- =	
					_ =	
		- 1-			_ =	
					= :	
			0	CCUPANT C	ONTACT WORKSHEET	
Contact	I Co	nterior mponent entacted	Occupant No. if Known	Body Region if Known	Supporting Physical Evidence	Confidence Level of Contact Point
Α	A-A	pillAa	On	Handfren	Black mark	3
В		11	//	11	Black mark cracked plastic Skiw on tood	3
С	I.	P	11	//	Skiw on tood	2
D	Ku	e bolsten	11	u. Knee	Scuft	/
E						
F						
G						
Н						
ı						
J						



CODES FOR COLUMN B, OCCUPANT SPACE NUMBER

OCCUPANT SPACE NUMBER IS A TWO-DIGIT CODE. THE USE OF THE CODE IS DETERMINED BY THE VEHICLE SEAT CONFIGURATION AT THE TIME OF THE ACCIDENT.

FIRST DIGIT

THE FIRST DIGIT (LEFT DIGIT) DENOTES THE SEAT ROW, WITH CODE VALUES FROM 1 TO 5.

SECOND DIGIT

THE SECOND DIGIT (RIGHT DIGIT) DENOTES THE POSITION ON THE SEAT AND, IN SOME INSTANCES, THE WIDTH OF THE SEAT.


(1) LEFT	(3) RIGHT		. INDIVIDUAL SEAT
(1) LEFT	(2) CENTER	(3) RIGHT	BENCH: FULL WIDTH 3 PASSENGER
(1) LEFT	(2) LEFT CENTER	(6) RIGHT (3) RIGHT	BENCH: FULL WIDTH 4 PASSENGER
(1) LEFT	(2) CENTER	(5) RIGHT &AISLE SPACE	BENCH: PARTIAL WIDTH, LEFT
(0) LEFT & SPACE	(2) CENTER	(5) RIGHT &SPACE	BENCH: PARTIAL WIDTH, CENTERED
(4) ENTIRE	VEHICLE WIDTH		. CARGO AREA

EXAMPLES

THE TWO FIGURES BELOW PROVIDE EXAMPLES OF THE OCCUPANT SPACE NUMBER.

PASSENGER CAR 5 PASSENGERS

VAN 12 PASSENGER CAPACITY



CODES FOR COLUMN F, MEASUREMENT AXIS

(X) X-AXIS (FORE & AFT)

(Y) Y-AXIS (LATERAL)

(Z) Z-AXIS (VERTICAL)

CODES FOR COLUMNS G, H, I & J, OCCUPANT & INJURY NUMBERS

OCCUPANT NUMBER	INJURY NUMBER	CONTACT
(OO) (##)	(00) (00)	NO CONTACT CONTACT, NO INJURY
(97) (99)	(99) (00) OR (99)	CONTACT, NO INJURY UNKNOWN, INJURY UNKNOWN UNKNOWN IF CONTACT

CODES FOR COLUMN C, INTRUDING COMPONENT OR OBJECT

NOTE: DO NOT CODE OBJECTS OTHER THAN COMPONENTS OF CASE VEHICLE.

INDIVIDUAL COMPONENT

INTERNAL

- (01) INSTRUMENT PANEL
- (02) FIRE WALL
- (03) TOE PAN
- (04) FLOOR PAN
- (05) STEERING COLUMN
- (06) WINDSHIELD
- (07) WINDSHIELD HEADER
- (08) A-PILLAR
- (09) DOOR PANEL OR SIDE PANEL
- (10) WINDOW FRAME
- (11) B-PILLAR
- (12) C-PILLAR
- (13) D-PILLAR
- (14) ROOF SIDE RAILS (15) ROOF OR CONVERTIBLE TOP
- (16) BACKLIGHT HEADER
- (17) FRONT SEAT-BACK SURFACE/ SEAT-BACK BACK SURFACE
- (18) SECOND SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (19) THIRD SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (20) FOURTH SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (21) FIFTH SEAT-BACK SURFACE SEAT-BACK BACK SURFACE
- (22) BACK PANEL/BACK DOOR SURFACE
- (23) SEAT CUSHION SURFACE/EDGE
- (24) CONSOLE
- (25) OTHER (DESCRIBE)
- (26) UNKNOWN INTERNAL SURFACES
- (28) TRANSMISSION TUNNEL (HUMP)
- (29) SIDE FOOTWELL PANEL (KICKPANEL)
- (30) SILL

EXTERNAL

- (43) HOOD
- (44) OBJECT EXTERNAL TO PASSENGER COMPARTMENT BUT PART OF CASE VEHICLE
- (45) OUTSIDE SURFACE OF CASE VEHICLE (46) OTHER (E.G. SPARE TIRE,
- JACK. DESCRIBE.) (49) UNKNOWN EXTERNAL OBJECT

GROUPED FOR MASSIVE INTRUSION INTO AN OCCUPANT SPACE

USE ONLY IF ALL THESE COMPONENTS INTRUDED INTO A SINGLE OCCUPANT SPACE.

- (50)WINDSHIELD HEADER A-PILLAR
 - ROOF SIDE RAIL
- (51)INSTRUMENT PANEL A-PILLAR DOOR PANEL
- (52)INSTRUMENT PANEL A-PILLAR WINDSHIELD HEADER
- (53)DOOR PANEL **B-PILLAR ROOF RAIL**
- (54)DOOR PANEL A-PILLAR **ROOF RAIL**
- (55)INSTRUMENT PANEL FLOOR PAN A-PILLAR DOOR FRAME
- A-PILLAR **B-PILLAR** WINDOW FRAME

(56)ROOF RAIL

- (57)ROOF RAIL A-PILLAR **B-PILLAR** C-PILLAR DOOR PANEL
- (58)ROOF **ROOF RAIL** WINDOW FRAME **DOOR PANEL**
- (59)BACKLIGHT HEADER **ROOF** C-PILLAR THIRD SEAT-BACK

- (60)ROOF **ROOF RAIL** A-PILLAR **B-PILLAR** C-PILLAR WINDOW FRAME DOOR PANEL FLOOR PAN
- (61)INSTRUMENT PANEL TOE PAN WINDSHIELD HEADER A-PILLAR ROOF RAIL WINDOW FRAME DOOR PANEL ROOF
- (62)ROOF **ROOF RAIL** C-PILLAR WINDOW FRAME FLOOR PAN SECOND SEAT DOOR PANEL
- (63)ROOF RAIL ROOF **B-PILLAR** WINDOW FRAME FLOOR PAN DOOR PANEL SECOND SEAT FRONT SEAT
- (64)ROOF RAIL ROOF OR CONVERTIBLE TOP A-PILLAR **B-PILLAR** WINDOW FRAME WINDOW HEADER
- (65)WINDSHIELD WINDSHIELD HEADER **ROOF SIDE RAIL**
- (66)WINDSHIELD WINDSHIELD HEADER A-PILLAR

(98)NOT APPLICABLE

(99)UNKNOWN

Duplicate columns 1-8 Module from the previous card.	I T Format 0 1 1 12			INTR	IUSION	IT-5
WAS THERE OCCUPANT COM (0) NO <u>DO NOT</u> ANSWER NEXT (1) YES <u>ANSWER</u> NEXT QUESTI (9) UNKNOWN <u>SKIP PAGE</u> .	QUESTION. <u>SKIP PAGE</u> .	N? <u>\bigcirc</u> V	VAS INTRUSIOI (0) NO <u>co</u> (1) YES <u>sk</u>	MPLETE PAG		14
Duplicate columns 1-8 Module from the previous card. NOTE: Each line in the table below i	I T Format 0 2 9 10 11 12 s a separate record (card).	Duplicate column	s 1 - 12 for each c	ompleted lii	ne.	
	RUSIONS IN THIS ORDE OR B, F, G, H, I, J ON I OR C ON PAGE IT-4	R: LEFT TO RIGHT PAGE IT-3	ON ROW; FRON			S.
A B C INTRUDING A INTRUSION OCC. COMPONENT NUMBER SPACE NO. OR OBJECT	ASSOC. MAXIMUM MAX EVENT INTRUSION INTR	F G KIMUM MAXIMUM USION INTRUSION IS (cm) Z AXIS (cm)	1	I INJURY NUMBER	J OCCUPANT NUMBER	K INJURY NUMBER
13-14 15-16 17-18	19 20-21 22	2-23 24-25	26-27	28-29	30-31	32-33
0 1 0 2 0 3 0 4 0 5 0 6 0 7 NOTE: USE ADDITIONAL PAGE IF MORE THAT Duplicate columns 1-8 from the previous card. Module 1						
NOTE: IF NO SIDE DOOR INTRUSION, SKIP REMAINDER OF PAGE. SIDE DOOR INTRUSION RESULTED FROM INTRUSION NUMBER CAUSE CODES FOR CAUSE: 13 15 (1) DIRECT IMPACT IMPACT 16 18 (2) INDUCED DAMAGE 19 21 (9) UNKNOWN	IF DAMAG DOOR INT INTRUSION NUMBER A	DAMAGED COMPONENT 1	COMPONEN DAMAGE	T ED NT 2 F () () () () ()	CODES CODES COMPONE O) NONE 1) A-PILLAR 2) B-PILLAR 3) C-PILLAR 4) LATCH/STRI 5) HINGES 7) OTHER:	KER

Duplicate columns 1-8 from the previous card.

Intrusion

IT-6

NOTE: Each line in the table below is a separate record (card).

Duplicate columns 1 - 12 for each completed line.

-- ADDITIONAL PAGE --

INTRUSIONS CODE INTRUSIONS IN THIS ORDER: LEFT TO RIGHT ON ROW; FRONT TO BACK IN VEHICLES.

CODES FOR B, F, G, H, I, J ON PAGE IT-3

CODES FOR C ON PAGE IT-4

OCCUPANT CONTACT AND INJURY

									1	
Α	В	C INTRUDING	D ASSOC.	E MAXIMUM	F MAXIMUM	G MAXIMUM	н	ı	J	K
INTRUSION NUMBER	OCC. SPACE NO.	COMPONENT OR OBJECT		INTRUSION	INTRUSION Y AXIS (cm)	INTRUSION	OCCUPANT NUMBER	INJURY NUMBER	OCCUPANT NUMBER	INJURY NUMBER
13-14	15-16	17-18	19	20-21	22-23	24-25	26-27	28-29	30-31	32-33
0 8								<u>.</u>		
0 9			_							
1 0										
1 1										
1 2										
<u>1</u> 3										
1 4										
<u>1</u> 5			-							
<u>1 6</u>										
1 7										
<u>1</u> 8										
<u>1</u> 9										
2 0										
<u>2</u> <u>1</u>										
2 2										
2 3										
2 5										


Duplicate columns 1-8 from the previous card.	Modu	ile <u>I</u> D	Format 0 1 12	In	ITERIOR DAMAGE	ID-1			
co	CODES: (0) NO (4) YES, and OCCUPANT CONTACT (1) YES (3) NO, and OCCUPANT CONTACT (9) UNKNOWN								
SIDES FRONT DOOR FRONT HARDWARE FRONT ARMREST FRONT GLASS REAR DOOR AREA REAR HARDWARE REAR ARMREST REAR GLASS ROOF SIDE RAIL B-PILLAR C-PILLAR D-PILLAR HEADLINING ROOF STRUCTURE T-ROOF/SUN ROOF	LEFT O 13 O 15 O 17 O 19 O 23 O 25 O 27 O 29 O 31 O 33 O 37 O 39 O 41	RIGHT 0 4 0 6 0 8 0 2 0 2 0 2 0 8 0 8 0 8 0 8 0 8 0 8	FRONT FOOT CONTROLS IGNITION KEYS REAR VIEW MIRROR SUNVISOR/FITTINGS (5) LEFT SIDE ONLY (6) RIGHT SIDE ONLY (7) BOTH SIDES WINDSHIELD TOP MOLDINGS LEFT A-PILLAR (UPPER OR LOWER) RIGHT A-PILLAR (UPPER OR LOWER) CENTER CONSOLE TRANSMISSION SELECTOR LEVER RIM, HORN, SPOKE	Q 45 Q 46 Q 47 Q 48 Q 9 1 50 0 51 0 52 0 53 0 54	INSTRUMENT PANEL UPPER PANEL MID PANEL LOWER PANEL ASHTRAY CONTROL KNOBS & LEVERS GLOVE COMPARTMENT AREA INSTRUMENTS PARKING BRAKE RELEASE PARKING BRAKE PEDAL A/C OR UPPER VENT OUTLET HEATER OR A/C DUCTS RADIO OTHER: *	0 550 58 0 59 0 60 60 60 60 666 67			
OTHER: *	41	\$\frac{42}{5}\$			REAR WINDOW WINDOW HEADER CONSOLES VERTICAL ROOF	O 68 O 70 65 71			

MORE THAN ONE ITEM MAY BE NOTED.

Duplicate columns 1-8 from the previous card. Module S T 9 10			SEATS	(ST-1
FRONT SEAT TYPE OF FRONT SEAT (00) NO SEAT (01) STANDARD BENCH (02) SPLIT BACK, 50-50 (03) SPLIT BACK, DRIVER WIDE (04) SPLIT BACK, PASS. WIDE (05) BUCKET (06) CAPTAIN'S CHAIR (07) INDIV. BENCH, 50-50 (08) INDIV. BENCH, DRIVER WIDE	DRIVER 0 5 13 14	PASSEN'R 0 5 16	FRONT SEAT-BACK SEAT-BACK TYPE (1) FORWARD FOLDING (2) RIGID (3) RECLINING (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	DRIVER 3 30	Passent 3
(09) INDIV. BENCH, PASS. WIDE (97) OTHER: (99) UNKNOWN TYPE OF SEAT MOUNT (1) STANDARD (2) PEDESTAL (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	17	18	SEAT-BACK LOCK TYPE (0) NONE (1) MANUAL (2) INERTIA (3) POWER (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	32	33
SWIVEL MECHANISM EQUIPPED (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	19	20	LOCKS HELD (0) NO (1) YES (8) NOT APPLICABLE	34	35
ORIGINAL EQUIPMENT SEATS (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN CONTACT OF SEAT BY REAR OCCUPANT (0) NO (1) YES (8) NOT APPLICABLE	<u>/</u> 21 <u>8</u> 23	\frac{1}{22}	(9) UNKNOWN RECLINER MECHANISM HELD (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	<u>/</u> 36	37
(9) UNKNOWN FRONT SEAT DAMAGE (0) NONE (1) BACKREST ONLY DAMAGED (2) CUSHION ONLY DAMAGED (3) BACKREST & CUSHION DAMAGED (8) NOT APPLICABLE (9) UNKNOWN	25	∂ 26	HEAD RESTRAINT HEAD RESTRAINT TYPE (0) NONE (1) ADJUSTABLE (2) INTEGRAL (3) NOT INTEGRAL, BUT CANNOT BE REMOVED (7) OTHER: (8) NOT APPLICABLE	<u>]</u>	39
CENTER ARMREST DAMAGED (0) NO (1) YES (7) EQUIPPED, DAMAGE UNKNOWN (8) NOT APPLICABLE (NO CENTER ARMREST) (9) UNKNOWN IF EQUIPPED	27	- 1	(9) UNKNOWN REMOVED PRE-CRASH (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN	40	<u>0</u>
FRONT SEAT ROTATION (0) NONE APPARENT (1) FORWARD APPARENT	<u>Ø</u>	<u>O</u>	ADJUSTMENT AT CRASH (1) UP (2) DOWN (8) NOT APPLICABLE (9) UNKNOWN HEAD RESTRAINT DAMAGE	<u>2</u>	43
(2) REARWARD APPARENT (3) LEFT APPARENT (4) RIGHT APPARENT (5) MULTIPLE ROTATIONS SPECIFY (8) NOT APPLICABLE (9) UNKNOWN			(0) NONE (1) DAMAGED BUT NOT SEPARATED (2) SEPARATED (8) NOT APPLICABLE (9) UNKNOWN	0 4	<u></u> <u>45</u>

			Si	EATS	ST-2
FRONT SEAT ADJUSTMENT	DRIVER	PASSEN'R	SECOND SEAT (CONT.)	0	
SEAT ADJUSTMENT TYPE (0) NONE (RIGID) (1) MANUAL (2) POWER (7) OTHER: (8) NOT APPLICABLE (NO SEAT) (9) UNKNOWN ADJUSTMENT PROVIDED (1) 2-WAY	46	47	(0) NO (1) YES (7) EQUIPPED, DAMAGE UNKNOWN (8) NOT APPLICABLE (NO CENTER ARMREST) (9) UNKNOWN IF EQUIPPED	4	9 50
(2) 4-WAY (3) 6-WAY (7) OTHER:	48	49	SECOND SEAT-BACK LOCKS	LEFT	Rіgнт
SEAT ADJUSTER DAMAGE (0) NONE (1) CHUCKING (FREE PLAY) (2) DEFORMED (RELEASED/JAMMED) (3) SEPARATED (7) OTHER: (8) NOT APPLICABLE (9) UNKNOWN	⊘ 50	51	FOR THE FOLLOWING, USE: (0) NO (1) YES (8) NOT APPLICABLE (9) UNKNOWN		
SEAT ADJUSTER SEPARATION (0) NONE (1) SEPARATED AT FLOOR (2) SEPARATION OF ADJUSTER (3) SEPARATED AT SEAT (8) NOT APPLICABLE (9) UNKNOWN	<u>8</u>	<u>&</u> 53	LEFT OR CENTER, EQUIPPED LEFT OR CENTER, HELD (3) SEAT FOLDED DOWN RIGHT, EQUIPPED	63 0 65	0 8 4 1 66
PRE-CRASH POSITION (1) FORWARD (2) MIDDLE (3) REARWARD (8) NOT APPLICABLE (9) UNKNOWN	2 54	3	RIGHT, HELD (3) SEAT FOLDED DOWN THIRD SEAT	67	68
SECOND SEAT	LEFT	Rіснт	EQUIPPED	0	0
TYPE OF SECOND SEAT (0) NONE (1) NON-FOLDING (2) FOLDING (3) CAPTAIN'S CHAIR (4) JUMP SEAT (5) INTEGRAL CHILD SEAT	<u>6</u>	6 57	BACKREST DAMAGED CUSHION DAMAGED	71 5 73	70 8 72 8 74
(6) LUGGAGE AREA ACCESS PANEL (9) UNKNOWN SECOND SEAT DAMAGE (0) NONE (1) BACKREST ONLY (DAMAGED OR LOOSENED) (2) CUSHION ONLY (DAMAGED OR LOOSENED) (3) BACKREST & CUSHION (DAMAGED OR LOOSENED) (4) INTEGRAL CHILD SEAT (PRIORITY CODE) (5) LUGGAGE AREA ACCESS PANEL (DAMAGED OR LOOSENED) (8) NOT APPLICABLE (9) UNKNOWN	₽ 58	59	VEHICLE EQUIPPED WITH REAR HEAD RESTRAINTS (0) NOT EQUIPPED (OR REMOVED) (1) EQUIPPED (2) EQUIPPED & DAMAGED (8) NOT APPLICABLE (NO REAR SEAT) (9) UNKNOWN Applies to any rear-seat position	1	75

Duplicate columns 1-8 Module A B Format C from the previous card.	1 12	AIRBAG	AB-1
DRIVER SIDE LOCATION OF AIRBAG STEERING WHEEL EQUIPPED (0) NO (1) YES (4) PRIOR DEPLOYMENT NOT REINSTALLED (9) UNKNOWN IF AIRBAG EQUIPPED DEPLOYED (0) NO (1) YES (2) PARTIAL/IMPROPER DEPLOYMENT (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	13	PASSENGER SIDE LOCATION OF AIRBAG INSTRUMENT PANEL (GLOVE BOX) EQUIPPED (0) NO (1) YES (4) PRIOR DEPLOYMENT NOT REINSTALLED (9) UNKNOWN IF AIRBAG EQUIPPED DEPLOYED (0) NO (1) YES (2) PARTIAL/IMPROPER DEPLOYMENT (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	16 L
CONDITION OF AIRBAG STEERING WHEEL (0) NO DAMAGE (2) SPLIT OR TORN (3) CUT DURING CRASH (4) BURNED/MELTED (5) CUT POST CRASH (6) OTHER (7) DAMAGED, CONDITION UNKNOWN (8) NOT APPLICABLE (NOT EQUIPPED NOT DEPLOYED) (9) UNKNOWN IF EQUIPPED OR CONDITION	<u>O</u> 15	CONDITION OF AIRBAG INSTRUMENT PANEL (GLOVE BOX) (0) NO DAMAGE (2) SPLIT OR TORN (3) CUT DURING CRASH (4) BURNED/MELTED (5) CUT POST CRASH (6) OTHER (7) DAMAGED, CONDITION UNKNOWN (8) NOT APPLICABLE (NOT EQUIPPED/NOT DEPLOYED) (9) UNKNOWN IF EQUIPPED OR CONDITION	18
DRIVER SIDE AIRBAG STEERING WHEEL TETHER (0) NO (1) YES (6) OTHER (7) UNKNOWN IF TETHERED (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN IF AIRBAG EQUIPPED	19	PASSENGER SIDE AIRBAG INSTRUMENT PANEL (GLOVE BOX) TETHER (0) NO (1) YES (6) OTHER (7) UNKNOWN IF TETHERED (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN IF AIRBAG EQUIPPED	21
MARKED BY CONTACT (0) NO (1) YES (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	20	MARKED BY CONTACT (0) NO (1) YES (8) NOT APPLICABLE (NO AIRBAG) (9) UNKNOWN	<u>Q</u>



NOTE TO THE INVESTIGATOR:

THE FOLLOWING TWO SECTIONS,
OCCUPANT INFORMATION AND INJURY CLASSIFICATION,
ARE TO BE FILLED IN
FOR EACH CASE VEHICLE OCCUPANT,
WHETHER INJURED OR NOT.


IF THERE IS MORE THAN ONE OCCUPANT,
USE ADDITIONAL COPIES
OF PAGES OC-1, OC-2, OC-3,
AND IC-2 TO DESCRIBE THEM
AND ATTACH THE COPIES TO THIS REPORT.


Duplicate columns 1-8 from the previous card. Module O C Format 0 9 10 11	2 12	OCCUPANT INFORMATION (OC-1
OCCUPANT IDENTIFICATION OCCUPANT NUMBER ROLE OF OCCUPANT AT 1ST IMPACT (1) MOTOR VEHICLE DRIVER (2) MOTOR VEHICLE PASSENGER (NOT DRIVER) (9) UNKNOWN	<u>0</u> <u>1</u> 14 <u>15</u>	PHYSICAL DESCRIPTION AGE IN YEARS (00) LESS THAN 1 YEAR (98) 98 YEARS OR OLDER (99) UNKNOWN AGE IN MONTHS (00) LESS THAN 1 MONTH (25) 25 MONTHS OR OLDER (99) UNKNOWN	51/20 21 25/20 23
OCCUPANT POSITION ROW LOCATION (1) FRONT (2) SECOND (3) THIRD (4) FOURTH (7) OTHER: (8) EXTERNAL TO PASSENGER COMPARTMENT (E.G. BED OF PICKUP) (9) UNKNOWN	16	MASS (kg) (999) UNKNOWN (340 16) HEIGHT (cm) (999) UNKNOWN (5 ft, 5; w) SEX (1) MALE (2) FEMALE (9) UNKNOWN	1 5 9 24 25 2 1 6 5 27 28 2 2 30
LATERAL LOCATION (1) LEFT (2) LEFT CENTER (3) CENTER (4) RIGHT CENTER (5) RIGHT (6) ALL (LYING ON SEAT) (8) EXTERNAL TO PASSENGER COMPARTMENT (9) UNKNOWN	17	MEDICAL CONDITIONS TREATMENT/MORTALITY (00) NONE (01) FIRST AID AT SCENE (02) TREATED AT HOSPITAL/CLINIC BUT NOT ADMITTED (03) HOSPITALIZED FOR OBSERVATION LESS THAN 24 HOURS (04) HOSPITALIZED OVER 24 HOURS OR FOR SIGNIFICANT TREATMENT (05) FATAL, DEAD AT SCENE (06) FATAL, DOA	<u>O</u> <u>Z</u>
POSTURE (10) SITTING ON SEAT (11) SITTING ON SEAT IN ABNORMAL POSITION (E.G. FEET ON DASH, SIDEWAYS) (12) SITTING ON CONSOLE (20) ON LAP OR IN ARMS (30) STANDING ON SEAT (40) STANDING ON FLOOR (47) STANDING EXTERNAL TO PASSENGER COMPARTMENT (50) IN BASSINET	1 0 19	(07) FATAL, DEAD WITHIN 24 HOURS (08) FATAL, DEAD 24 HOURS TO 31 DAYS LATER (09) FATAL, DEAD 31 DAYS TO 1 YEAR LATER (10) FATAL DEAD WITHIN UNKNOWN PERIOD (99) UNKNOWN INJURY SEVERITY SCORE (ISS) (99) UNKNOWN	0 2 33 34
(60) IN CHILD SEAT (65) IN CHILD SEAT (65) IN CHILD HARNESS (70) LYING ON SEAT (80) LYING/SITTING ON PASSENGER FLOOR (83) LYING/SITTING ON OTHER OBJECT IN PASSENGER COMPARTMENT: (85) ON CARGO FLOOP/FOLDED SEAT-BACK (87) LYING/SITTING, EXTERNAL TO PASSENGER COMPARTMENT (97) OTHER: (99) UNKNOWN		NON-IMPACT MED. CONDITIONS (0) NONE (1) YES, TIME & TYPE UNKNOWN (2) PRE-CRASH FATAL (CLINICAL DEATH AT WHEEL) (3) PRE-CRASH NON-FATAL (E.G. PRIOR INJURY, STROKE) (4) PREGNANT (5) POST-CRASH FATAL (DROWNING) (6) POST-CRASH NON-FATAL INJURY (7) OTHER: (8) COMBINATION OF ABOVE (CIRCLE EACH) (9) UNKNOWN	<u>O</u> 35

		Occupant Information	OC-2
MEDICAL CONDITIONS (CONT.) POLICE INJURY SEVERITY CODE FOR THIS OCCUPANT (0) O - NO INJURY (1) C - POSSIBLE INJURY (2) B - NON-INCAPACITATING (3) A - INCAPACITATING INJURY (4) K - FATAL (5) INJURED, SEVERITY UNKNOWN (6) DIED PRIOR TO IMPACT (7) NON-FATAL INJURY, SEVERITY UNKNOWN (9) UNKNOWN	Z 36	CHILD SEAT TYPE (00) NONE USED (01) YES, USED (02) INTEGRAL, Chrysler Mini-van (88) NOT APPLICABLE (ADULT OR OLDER CHILD) (99) UNKNOWN CHILD SEAT MAKE/MODEL	8 41 42
ACTIVE RESTRAINT SYSTEM (0) NONE (1) LAP BELT (2) SHOULDER HARNESS ONLY (3) BOTH LAP BELT & SHOULDER HARNESS (9) UNKNOWN ACTIVE RESTRAINT SYSTEM USAGE (0) NONE (AVAILABLE BUT NOT USED) (1) LAP BELT ONLY (2) SHOULDER HARNESS ONLY (3) BOTH LAP BELT & SHOULDER HARNESS (7) IMPROPER USAGE (8) NOT APPLICABLE (NONE AVAILABLE) (9) UNKNOWN PASSIVE RESTRAINT SYSTEM (0) NONE (1) AIRBAG INSTALLED (2) PASSIVE UPPER TORSO WITH KNEE BOLSTERS (3) PASSIVE UPPER TORSO WITHOUT KNEE BOLSTERS (4) PASSIVE LAP & UPPER TORSO (5) AIRBAG INSTALLED & PASSIVE RESTRAINT (7) OTHER: (9) UNKNOWN PASSIVE RESTRAINT SYSTEM USAGE (0) SYSTEM DEFEATED (1) AIRBAG NOT DEPLOYED (2) AIRBAG DEPLOYED (3) AIRBAG NOT REINSTALLED (4) PASSIVE LAP & UPPER TORSO USED (5) PASSIVE UPPER TORSO USED (6) SYSTEM USED IN MANUAL MODE (7) IMPROPER USAGE (8) NOT APPLICABLE (NOT ORIGINALLY EQUIPPED) (9) UNKNOWN	3 3 37 0 39 2 40	EJECTION DEGREE OF EJECTION (0) NONE (1) PARTIAL (2) COMPLETE (7) EJECTED, DEGREE UNKNOWN (9) UNKNOWN IF EJECTED AREA OF EJECTION (01) WINDOW, LEFT SIDE (02) WINDOW, RIGHT SIDE (03) WINDOW, REAR (04) DOOR, LEFT SIDE (05) DOOR, RIGHT SIDE (06) DOOR, REAR OR TAILGATE (07) WINDSHIELD (08) ROOF OR OPEN CONVERTIBLE OR FROM EXTERNAL AREA (96) EJECTED AREA UNKNOWN (97) OTHER AREA: (98) NOT APPLICABLE (NOT EJECTED) (99) UNKNOWN IF EJECTED IF OCCUPANT WAS EJECTED, DESCRIBE IN DETAIL BELOW: HEAD RESTRAINT HEAD RESTRAINT AVAILABLE FOR THIS POSITION (0) NOT EQUIPPED OR REMOVED (1) EQUIPPED (9) UNKNOWN	<u>O</u> 43 <u>9</u> 44 1 46

OCCUPANT EYEWEAR (0) NONE (1) GLASSES (2) CONTACTS (3) BOTH GLASSES AND CONTACTS (4) OTHER (8) NOT APPLICABLE (9) UNKNOWN OCCUPANT INFORMATION OC-3 SOURCE OF INFORMATION (2) AUTOPSY (3) POLICE (4) OTHER (5) LAY CORONER/EXTERNAL EXAM (7) COMBINATION OF ABOVE (CIRCLE) (8) NOT APPLICABLE (9) UNKNOWN

INDICATE LOCATION OF INJURIES.





Duplicate columns 1-8 from the previous card.

Module <u>I</u> <u>C</u> Format <u>0</u> <u>1</u> 12

NOTE: Each line in the table below is a separate record (card).


Duplicate columns 1 - 12 for each completed line.

OCCUPANT INJURY CLASSIFICATION

						PRIMARY OIC				А	ssoc	IATE		СОММЕ	ENTS	
OCCUPANT NUMBER	INJURY NUMBER	PROBAL START I IN 1ST C	BILITY (HOI WITH MOST CONTACT A	IN ORDER OF RIZONTALLY) . I PROBABLE IREA COLUMN. BLE CONTACT	BODY REGION 1	ASPECT Q	LESION 3	SYSTEM/ORGAN 4	SEVERITY 15	BODY REGION 1	ASPECT 2	LESION 3	SYSTEM/ORGAN 4	SEVERITY US		
13-14	15-16	17-18	19-20	COMMENTS	21	22	23	24	25	26	27	28	29	30		
<u>01</u>	<u>0</u> <u>1</u>	87			<u>c</u>	<u>c</u>	<u>C</u>	I	1	_	_	_	_	_		
†	<u>02</u>	87			<u>c</u>	K	<u>_</u>	I	1		_	_	_	_		
	<u>03</u>	65			M	<u>s</u>	<u></u>	I	1		_	_	_			
	04	98			8	Į	<u>T</u>	M	1		_	_		_		
	05	56			K	<u>L</u>	A	Į	<u>1</u>					_		
	<u>06</u>	87			R	<u>L</u>	A	Ī	1			*****				
	<u>07</u>	87	47		A	<u>L</u>	A	I	1		_		_	_		
ej						_			_	_		. <u> </u>	_	_		
te "Occupant Number" for each line.					_	_	_			_	_		_			
lumber" f					_			_		_	_		_	-		
cupant N					_	_	_		-	_						
icate "Oc					_	_			-			_	_	_		
— Duplical					_		_	_	-				-	-		
					_		_		-		_			-		
					_	_	_	_	-				_	-		
					_	_			-		*****	_	_	-		
						_	_	_	-		_		_	-		
			ES IF NEC		_	_	_			_				_		

CODES FOR AREAS OF POSSIBLE OCCUPANT CONTACT

	OBEST SITALEAS OF TO	SSIBLE OCCUPA!	NI CONTACT
FRONT	FOF PASSENGER COMPARTMENT	Cinco	
	SUNVISOR, FITTING(S) &/OR TOP MOLDING	SIDES	
	WINDSHIELD	(20)	
(12	.) WINDSHIELD	(19)	HARDWARE ON SIDE OR DOOR
(0.5	" INOTO MENT DANE! (ODCOMO ADDAMA	(13)	ARMREST ON SIDE OR DOOR
(05		(24)	COAT HOOK
(54	•		
(55	•	(22)	WINDOW GLASS (SIDE)
(56	i) LOWER INSTRUMENT PANEL (Z)	(21)	
(81) ASH TRAY (INSTRUMENT PANEL)	` '	(5.52)
(02) GLOVE COMPARTMENT AREA	(26)	ROOF SIDE RAIL
(47) AIRBAG (ACRS) COMPARTMENT DOOR/COVER	, ,	A-PILLAR
		, ,	B-PILLAR
(57) BENEATH INSTRUMENT PANEL	• •	C-PILLAR
(53		(17)	
(48	•	(17)	D-FILLAR
(86		FLOOR	
(00)	, VEITHORE GOINGGEE		5.000
(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)	(40)	
(20)	FOOT CONTROLS (INCL. FARKING BRAKE PEDAL)	(27)	
(00)	CTEEDING ACCEMBLY (CREOUSIG AREA (MACCAMA)	(44)	The state of the s
(09)	,	(85)	
(65)		(28)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)
(66)		(91)	KICKPANEL
(59)	TRANSMISSION LEVER ON COLUMN		
		Roof	
(03)	HARDWARE ITEM (SPECIFIC AREA UNKNOWN)	(25)	ROOF OR CONVERTIBLE TOP
(82)		(10)	SUNVISOR, FITTING(S) &/OR TOP MOLDING
(83)	CONTROL KNOB(S) & LEVER(S) (FRONT)	(26)	
(84)	PARKING BRAKE HANDLE IN FRONT	(24)	
(67)	IGNITION KEY	(18)	
(06)		· (39)	
(04)		(68)	
(01)		, ,	
(08)		(69)	ROLL BAR
(58)	· · ·	F.,	
(68)	• • • • • • • • • • • • • • • • • • • •	EXTERIO	OR SURFACE OF CASE VEHICLE
(66)	ROOF MOUNTED CONTROLS/CONSOLES	(37)	OUTSIDE SURFACE OF CASE VEHICLE
D			(SPECIFIC AREA UNKNOWN)
REAR		(35)	HOOD OF CASE VEHICLE
(88)		(60)	EXTERIOR OF CASE VEHICLE (E.G.
(23)			OUTSIDE MIRRORS, ANTENNA, TRIM)
(39)	REAR WINDOW HEADER	(62)	EXTERIOR SIDE ROOF RAIL OF CASE VEHICLE
(50)	REAR SEAT CUSHION & BACK	(63)	TRUNK LID OF CASE VEHICLE
		(64)	TIRES OF CASE VEHICLE
INTERIO	R-GENERAL	(0.1)	THEO OF OACE VEHICLE
(11)	TRANSMISSION SELECTION LEVER (LOCATION UNK.)	BEYOND	CASE VEHICLE BOUNDARY
(59)	TRANSMISSION LEVER ON STEERING COLUMN	(36)	APEA EVITEDIOD TO CAR (COROUTIO ADEA LINE)
(44)	TRANSMISSION LEVER ON FLOOR OR CONSOLE	(30)	AREA EXTERIOR TO CAR (SPECIFIC AREA UNK.)
(07)		(70)	HOOD OF OTHER VEHICLE
(84)	PARKING BRAKE HANDLE IN FRONT	(71)	OTHER VEHICLE EXTERIOR HARDWARE (E.G.
(85)	PARKING BRAKE HANDLE ON FLOOR OR CONSOLE		OUTSIDE MIRRORS, ANTENNA, TRIM)
(28)	FOOT CONTROL S (INCL. PARKING PRAKE PERAL)	(73)	EXTERIOR SIDE ROOF RAIL OF OTHER VEHICLE
(20)	FOOT CONTROLS (INCL. PARKING BRAKE PEDAL)	(74)	HEADLIGHT OR FRONT GRILL OF OTHER VEH.
(00)	EPONT SEAT PACK(S)	(75)	TRUNK OF OTHER VEHICLE
(29)	FRONT SEAT-BACK(S)	(76)	OUTSIDE SURFACE OF OTHER VEHICLE
(51)	FRONT SEAT CUSHION	(77)	TIRES OF OTHER VEHICLE
(50)		(78)	GROUND
(49)		(79)	WATER
(89)	UNDER SEAT BOTTOM	(80)	EXTERIOR OBJECT (NOT VEHICLE, GROUND,
		(/	OR WATER. PLEASE DESCRIBE.)
(33)	RESTRAINT SYSTEM HARDWARE		THE TENDE DESCRIBE.
(34)	RESTRAINT SYSTEM WEBBING	PENETRA	ATING OBJECTS
(87)			
(47)	AIRBAG (ACRS) COMPARTMENT DOOR/COVER		OTHER VEHICLE
(46)		(72)	OBJECTS (DESCRIBE)
(48)		Moore	ANFOLIO
(30)		MISCELL	
(42)			NO CONTACT (INVALID FIELD FORM CODE)
			OTHER (E.G. FIRE. DESCRIBE)
(43)			SPARE TIRE
	INTERIOR LOOSE OBJECT	(96)	INDUCED
(32)		(97)	EJECTED, UNKNOWN CONTACT
	INTERNAL FLYING GLASS (FROM ANY SOURCE)	(98)	IMPACT FORCE, "WHIPLASH",
(41)	UNKNOWN INTERIOR SURFACE		HYPEREXTENSION/COMPRESSION
		(99)	UNKNOWN AREA OF CONTACT



CODES FOR OCCUPANT INJURY CLASSIFICATION (OIC)

BODY REGION

- (H) HEAD/SKULL
- (F) FACE
- (N) NECK
- (S) SHOULDER
- (X) UPPER EXTREMITIES
- (A) ARM (UPPER)
- (E) ELBOW
- (R) FOREARM
- (W) WRIST/HAND
- (C) CHEST
- (M) ABDOMEN
- (B) BACK
- (P) PELVIC/HIP
- (Y) LOWER EXTREMITIES
- (T) THIGH
- (K) KNEE
- (L) LEG (LOWER)
- (Q) ANKLE/FOOT
- (O) WHOLE BODY
- (U) UNKNOWN

3 LESION

- (L) LACERATION
- (C) CONTUSION
- (A) ABRASION
- (F) FRACTURE
- (P) PERFORATION, PUNCTURE
- (K) CONCUSSION
- (V) AVULSION
- (R) RUPTURE
- (S) SPRAIN
- (D) DISLOCATION
- (N) CRUSH
- (M) AMPUTATION
- (B) BURN
- (G) DETACHMENT, SEPARATION
- (Z) FRACTURE AND DISLOCATION
- (T) STRAIN
- (E) TOTAL SEVERANCE, TRANSECTION
- (O) OTHER
- (U) UNKNOWN

4 SYSTEM/ORGAN

- (S) SKELETAL
- (V) VERTEBRAE
- (J) JOINTS
- (D) DIGESTIVE
- (L) LIVER
- (N) NERVOUS SYSTEM
- (B) BRAIN
- (C) SPINAL CORD
- (E) EARS
- (O) EYES
- (A) ARTERIES
- (H) HEART
- (Q) SPLEEN
- (G) UROGENITAL
- (K) KIDNEYS
- (R) RESPIRATORY
- (P) PULMONARY/LUNGS
- (M) MUSCLES
- (T) THYROID, OTHER ENDOCRINE GLAND
- (I) INTEGUMENTARY (SKIN)
- (W) ALL SYSTEMS IN REGION
- (U) UNKNOWN

2 ASPECT

- (R) RIGHT
- (L) LEFT
- (B) BILATERAL
- (C) CENTRAL
- (A) ANTERIOR/FRONT
- (P) POSTERIOR/BACK
- (S) SUPERIOR/UPPER
- (I) INFERIOR/LOWER
- (W) WHOLE REGION
 (U) UNKNOWN

SEVERITY
SYSTEM/ORGAN
LESION
ASPECT
BODY REGION

1 2 3 4 5

5 SEVERITY (OR "AIS", ABBREVIATED INJURY SCALE)

- (0) NONE
- (1) MINOR
- (2) MODERATE
- (3) SERIOUS
- (4) SEVERE
- (5) CRITICAL
- (6) MAXIMUM
- (9) UNKNOWN





17900#2

















N 17900 #



117900 #11





















17900#21

















































